## State of New Mexico Energy, Minerals and Natural Resources Department OH CONSERVATION DIVISION

CONDITIONS OF APPROVAL, IF ANY:

54-41 - 2	Revised 1-1-89
L API NO. 30-015-234	109

O. Drawer DD, Artesia, NM 88210	TRICTI  1. Box 1980, Hobbs, NM 88240  P.O. Box 2088		WELL API NO. 30-015-23409			
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO ORALL OR TO DEEPER OR PLOG &CRATO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMANTENA OFFICE (FCRAM COIN) FOR SUCH PROPOSALS  Typ of Well Well Well Well Well Well Well Wel	DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe,	, New Mexico		5. Indicate Type of Lease STATE X	FEE 🗌
(DO NOT USE THIS PORM FOR PROPOSALS TO DRILL OF DEFENDENTIAL STATES AND CONTROL OF FREENOWS. USE TAPPUCATION FOR PERMANNITEDA, OFFICE (FORM C-101) FOR SUCH PROPOSALS)    Type of Walt	DISTRICT III 1000 Rio Brzzos Rd., Aztec, NM 87.	410		AUG 0 9 1991		
THE OTHER OF STATE OF	( DO NOT USE THIS FORM FOR	R PROPOSALS TO DRILL RESERVOIR. USE "APPL	CR TO DEEPEN I ICATION FOR PER	CH LERGI BHOKILO V		
E Neuro of Operator YATES PETROLEUM CORPORATION  7. Address of Operator 105 South 4th St., Artesia, NM 88210  6. Well Lossion Unit Letter G: 1980 Feet From The North 105 South 4th St., Artesia, NM 88210  6. Well Lossion Unit Letter G: 1980 Feet From The North 105 Range 28E NMPM Eddy Commy 105 Elevation (Show whether DF, RES, RT, CA, dac) 3544' CR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   PULL OR ALTER CASING   CHANGE PLANS   CASING TEST AND CEMENT JOS   DTHER: DTHER: DTHERT JOS   CASING TEST AND CEMENT JOS   DTHER: PULl CR ALTER CASING   OTHER: Pull RBP, downhole commingle world SEE RILE 103. 25-91. RB. U. Blew well down. Installed BOP. POOH with packer at 9600'. Will w/off/on tool 129800'. Latched onto RBP. POOH. Will w/packer on 2-7/8" tubing. Set at 9600'. Pulled BOP langed well up. Swabbed and flowed well. Released well to production 9.1 for commingling. Nownhole commingling the Morrow and Strawn granted by NMOCD Order DHC-803, as follows:  Strawn Pool: Oil 100%, Gas 94% Morrow Pool: Oil 0%, Gas 6%  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the information nows is mylind complete to the best of my troviceign and belief.  1 heavy contribute the mylind not not hear of my troviceign	OE GAS	<u> </u>	OTHER			:
Address of Operators 105 South 4th St., Artesia, NM 88210  (Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 8 Township 198 Rampe 28E NMFM Eddy Commy    10. Elevation (Stew wheather DF, RES, RT, GR, etc.)	Name of Operator	RPORATION			2	
Unit Lession  Unit Unit Lession  Unit Unit Lession  Unit Unit Lession  Unit Unit Lession  Unit Unit Unit Unit Unit Unit Unit Unit	. Address of Operator		3210		9. Pool name or Wildcat Millman Millman Strawn	an Morrow/
Section 8 Townships 17 10. Elevation (Shorw winters DF, RKS, RT, GR, etc.)  3544' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING CHANGE PLANS CASING FEST AND CEMENT JOB CASING FEST AND CEMENT JOB CHANGE PLUI OR ALTER CASING CHANGE PLUI RBP, downhole commingle production TOHER:  12 Describe Proposed or Completed Operations (Clearly state all partinent datasit, and give pertinent dates, including estimated date of storing arry proposed worth) SEE RULE 1103.  -25-91. RU. Blew well down. Installed BOP. POOH with packer at 9600'. WIH w/off/or tool 1 19800'. Latched onto RBP. POOR. WIH w/packer on 2-7/8" tubing. Set at 9600'. Pulled BOP langed well up. Swabbed and flowed well. Released well to production 8-1-91 for commingling. Nownhole commingling the Morrow and Strawn granted by NMOCD Order DHC-803, as follows:  Strawn Pool: Oil 100%, Gas 94% Morrow Pool: Oil 0%, Gas 6%  I benety control that the information above is true/pad complete to the bot of my toxwedge and belief.  TILESPHONE NO. 505/748-1.  TILESPHONE NO. 505/748-1.  TILESPHONE NO. 505/748-1.  TILESPHONE NO. 505/748-1.  AUG 1 3 1991	Well Location			Line and 1980	Feet From The East	Line
10. Elevasion (Show whether Dr. M. C. H. C.	Section 8	Township 19	S R2		NMPM Eddy	County
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK		10. Elev	ation (Snow whether .			
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DFILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  PLUG AND ABANDONMENT  TOTHER:  DITHER: DITHER: DOTHER: Pull RBP, downhole commingle  Production  TOTHER: Pull RBP, downhole commingle  TOTHER: Pull RBP, downhole  TOTHER: Pull RBP	//////////////////////////////////////	eck Appropriate Bo	ox to Indicate I	Nature of Notice, F	Report, or Other Data	_
EMPCRARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: Pull RBP, downhole commingle production  12 Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  -25-91. RU. Blew well down. Installed BOP. POOH with packer at 9600'. WIH w/off/on tool to 9800'. Latched onto RBP. POOH. WIH w/packer on 2-7/8" tubing. Set at 9600'. Pulled BOP langed well up. Swabbed and flowed well. Released well to production 8-1-91 for commingling. ownhole commingling the Morrow and Strawn granted by NMOCD Order DHC-803, as follows:  Strawn Pool: 0il 100%, Gas 94% Morrow Pool: 0il 0%, Gas 6%  Thereby contry that the information above is Tay Find complete to the best of my knowledge and belief.  SUNATURE THE Production Supervisor DATE  THE Production Supervisor DATE  THE Production Supervisor DATE  THE PRODUCTION AUG 1 3 1991				SUE	3SEQUENT REPORT OF	<del>-</del> :
ULL OR ALTER CASING  CASING TEST AND CEMENT JOB  OTHER: Pull RBP, downhole commingle production  12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103.  -25-91. RU. Blew well down. Installed BOR. POOH with packer at 9600'. WIH w/off/on tool to 9800'. Latched onto RBP. POOH. WIH w/packer on 2-7/8" tubing. Set at 9600'. Pulled BOP langed well up. Swabbed and flowed well. Released well to production 8-1-91 for commingling. ownhole commingling the Morrow and Strawn granted by NMOCD Order DHC-803, as follows:  Strawn Pool: 0il 100%, Gas 94% Morrow Pool: 0il 0%, Gas 6%  I heartly certof that the information above is true and complete to the best of my knowledge and bedief.  SKONATURE ALL ALL TIME Production Supervisor DATE  TIME Production Supervisor DATE  TIME Production Supervisor DATE  TIME Production Supervisor DATE  TIME PRODUCTION SUPERVISOR NO. 505/748-1	ERFORM REMEDIAL WORK	PLUG AND	ABANDON	REMEDIAL WORK		
OTHER: Pull RBP, downhole commingle production  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  -25-91. RU. Blew well down. Installed BOP. POOH with packer at 9600'. WIH w/off/on tool to 9800'. Latched onto RBP. POOH. WIH w/packer on 2-7/8" tubing. Set at 9600'. Pulled BOP langed well up. Swabbed and flowed well. Released well to production 8-1-91 for commingling. Sumhole commingling the Morrow and Strawn granted by NMOCD Order DHC-803, as follows:  Strawn Pool: 0il 100%, Gas 94% Morrow Pool: 0il 0%, Gas 6%  Inhereby conflythan the information above is true/had complete to the best of my knowledge and belief.  INDEPENDENT NAME  Juanita Goodlett  THE Production Supervisor  DATE  AUG 1 3 1991  AUG 1 3 1991	EMPORARILY ABANDON	CHANGE PL	ANS	COMMENCE DRILLIN	IG OPNS. PLUG AND AB	ANDONMENT
OTHER: FITT RDT, downton   December   Dece	PULL OR ALTER CASING			1		لتنا
Strawn Pool: Oil 100%, Gas 94%   Morrow Pool: Oil 0%, Gas 6%   M	OTHER:			OTHER: Pull RB	P, downhole commingle production	X
Morrow Pool: 0il 0%, Gas 6%  I hereby cerufy that the information above is true had complete to the best of my knowledge and belief.  SKINATURE:	work) SEE RULE 1103.  -25-91. RU. Blew to the second of th	well down. Instanto RBP. POOH. bbed and flowed the Morrow and	with w/packwell. Release	POOH with pac ker on 2-7/8" t	ker at 9600'. WIH w/o ubing. Set at 9600'. production 8-1-91 for c	ff/on tool Pulled BOP commingling.
SECUNATURE JUANITA GOODLETT THE Production Supervisor DATE 0-0-91  TYPE CRUPTURY NAME JUANITA GOODLETT TELEPHONE NO. 505/748-14  (This space for State Use) ORIGINAL SIGNED BY  ANK E WILL LAMS		· · ·	Gas 6%			
SIGNATURES JUANITA O DILICIT TITLE Production Supervisor DATE OF STATE OF STATE Uses DATE OF STATE Uses ORIGINAL SIGNED BY  AUG 1 3 1991	I hereby certify that the information ab	ove is true/and complete to the b	est of my knowledge an	d belief.		0.01
TYPE CREPTENT NAME  Juanita Goodlett  (This space for State Use)  ORIGINAL SIGNED BY  AUG 1 3 1991		Donilles	7n	mr Production	Supervisor DATE	
(This space for State Use) ORIGINAL SIGNED BY  AUG 1 3 1991	//	ianita Goodlett			TELEPHONE :	±0. 505/748−14
	<b>O</b> 11.1		; :			6 1 3 1991