

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

AUG - 2 1993

C. I. D.

WELL API NO. 30-015-23412
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. L-4673
7. Lease Name or Unit Agreement Name State "36"
8. Well No. 1
9. Pool name or Wildcat Undesignated Atoka

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐	
2. Name of Operator Mitchell Energy Corporation	
3. Address of Operator Box 4000, The Woodlands, TX 77387	
4. Well Location Unit Letter B : 750 Feet From The North Line and 2173 Feet From The East Line Section 36 Township 19S Range 21E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4245' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU. NU BOP. Release pkr @ 7100' and POOH w/2 3/8" tbq and pkr. RIH w/CIBP setting @ 7180'. Dump bail 35' of cement on top. RIH w/2 3/8" tbq. Load hole w/9.5 ppg mud. Spot 25 sx cement plugs 7000-6700' (Strawn), 6400-6100' (Canyon), 5880-5580' (Penn), & 4800-4500' (DV tool). POOH w/2 3/8" tbq. RIH w/csg cutter and cut 4 1/2" casing at ±4000'. POOH w/4 1/2" csg. RIH w/tbq spotting 25 sx plug 4050-3935' (csg stub), 30 sx 3520-3420' (Abo), 30 sx 2060-1960' (8 5/8" shoe, this plug must be tagged), 30 sx 1550-1460' (Glorieta), & 322'-surface. Erect P&A marker. RDMO PU. All plugs per verbal recommendation (7/22/93) of Mr. Mark Ashley, OCD, Artesia.

* Tag Stub Plug

Notify N.M.O.C.C. in sufficient time to witness

Huggins

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Greg Colburn*

Staff Prod Eng

7/26/93

TYPE OR PRINT NAME: Greg Colburn

TELEPHONE NO. (915)682-5396

(This space for State Use)

APPROVED BY *[Signature]*

TITLE *Field Rep*

DATE 8/31/93

CONDITIONS OF APPROVAL, IF ANY: