STATE OF NEW MEXICO	
NERGY AND MINERALS DEPARTMENT JIL CONSERVATION DIVISION   DISTRUBUTION P. O. BOX 2088   SANTA FE J	Form C-103 Revised 10-1-78
U.S.O.S. LAND OFFICE OPERATOR	Sa. Indicate Type of Leise State State Foe X S. State OII & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OF PLUG PACK TO A DIFFERENT RESTANDIA.	7. Unit Agreement Name
oric X GAS well X well other. MAY 2:0:1981 Yates Petroleum Corporation √	8. Farm or Lease Name Glass-Kincaid "OS"
207 South 4th St., Artesia, NM 88210 ARTESIA, OFFICE	9. Well No. 1
Location of Well D 330 FEET FROM THE North LINE AND 330 FEET FROM	10. Field and Pool, or Wildcat Und. Penasco Draw-SA-Yeso
West 7 19S 25E	
15. Elevation (Show whether DF, RT, GR, etc.) 3644.2' GR	12. County Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	
AFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK APPORARILY ABANDON COMMENCE DRILLING OPHS.	ALTERING CASING PLUG AND ABANDONMENT
OTHER	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3100' Ran 76 jts of  $4\frac{1}{2}$ " 9.5# J-55 casing set at 3097. Cemented w/350 sacks 50-50 Poz, .5# CF-9 & 2% KCL. PD 3:35 PM 4-27-81. Bumped plug to 1500 psi, released pressure & float held okay. Circulated 30 sacks to pit. WOC. WIH w/Steel Strip gun on wireline & perforated 2853-3090' w/13 .50" holes as follows: 2853, 56, 58, 60, 3057, 59, 61, 63, 65, 3084, 86, 88 & 90'. WIH w/Uni VI packer on 2-3/8" tubing. Acidized perfs 3057-90' w/1000 gals 15% SHA acid. Pulled tubing & packer to frac well. Spotted 250 gals 15% regular acid across perforations at 2853-62'. Broke perforations down. Frac'd perforations 2853-3090' (via casing) w/20000 gals gelled water, 40000# sand & 750 gals 15% regular acid. WIH w/RBP & set above perforations. Spotted 24 bbls 15% regular acid. WIH w/Steel Strip gun on wireline & perforated 2296-2547' w/11 .50" holes as follows: 2296, 2348, 97, 2418, 59, 77, 88, 2506, 20, 25, & 47'. Broke perforations down. WIH w/Steel Strip gun on wireline & perforated 2nd stage as follows: 2265-2549' w/18 .50" holes as follows: 2265, 78, 92, 2306, 52, 86, 2403, 16, 20, 57, 65, 80, 86, 91, 2518, 23, 45, 49'. Frac'd (via casing) w/2000 gals 15% regular acid, 60000 gals gelled water & 90000# sand (10000# 100 mesh & 80000# 20/40 sand). Set pumping equipment. Pumping back load.

Č.,		
ro. <u></u>	Engineering Secretary	<u>5/19/81</u>
over Mahe huthan	OIL AND GAS INSPECTOR	MAY 2 2 1981