taice	Energy, Minerals and Natur		Form C-103 SF1 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA' P.O. Box	FION DIVISION	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Me:		30-015-23564 5. Indicate Type of Lease STATE FEE XX
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 8741	0		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well: OfL WELL X WELL	OTHER		Bradshaw
2. Name of Operator		AUG 30.'94	8. Well No.
YATES PETROLEUM COR	PORATION		1
3. Address of Operator	reet - Artesia, NM 88	O. C. D. 210 ARTESIA, OFFICE	9. Pool name or Wildcat Penasco Draw Upper Penn
4. Well Location	leet - Altesia, Mi 00		
Unit Letter :	660 Feet From The South	Line and 660	Feet From The East Line
	Township 19S	Range 25E	NMPM Eddy County
Section 4	10. Elevation (Show w	whether DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
NOTICE OF			—
	PLUG AND ABANDON		
	CHANGE PLANS		
PULL OR ALTER CASING]	CASING TEST AND	
OTHER:		OTHER: Perfs	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
8-23-94 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. TOOH with 2-3/8" tubing. TIH w/casing guns and perforated 7828-7832' w/6 .42" holes (2 SPF) as follows: 7828, 31 & 7832'. TOOH with casing guns and rigged down wireline. TIH w/RBP, packer and 2-3/8" tubing. TIH w/1-11/16" GR tool. Correlated tools into place. TOOH with			
1-11/16" GR. Set RBP at 7890' and packer at 7857'. Shut down. 8-24-94 - Acidized perforations 7864-7868' w/2000 gallons 20% NEFE acid. Moved RBP to 7850' and tested to 1200#. Set packer at 7806'. Acidized perforations 7828-7832' w/3000			
gallons 20% NEFE aci	d. Perfs communicated	l with upper perfora	tions 7758-7794'. Moved
packer to 7726'. Acidized perforations 7758-7832' w/9000 gallons 20% NEFE acid and ball			
sealers. Straddled perforations 7758-7868' and rigged up swab. Swabbing. 8-25-94 - Swabbing.			
8-26-94 - Unset packer.and RBP. TOOH with 2-3/8" tubing, packer and RBP. Released to production to run sub-pump.			
production to full su	ը-հզահ.	· · · ·	
<u> </u>	e is true and complete to the best of my know	wledge and belief.	
I hereby certify that the information abov		mre Production	n Clerk рате8-29-94
SIGNATURE T USING		(IILE	505-748-1471 TELEPHONE NO.
TYPE OR PRINT NAME RUSTY Klein TELEPHONE NO.			
(This space for State Use)	INAN DISTRICT II		OCT 1 2 1994
SUPERV	ISOR. DISTRICT II	mle	DATE