

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
V-21

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Mesquite OG State
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER L 1650 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 18S RANGE 31E N.M.P.M.	10. Field and Pool, or Wildcat Shugart Yates-Qn-Grb
15. Elevation (Show whether DF, RF, GR, etc.) 3559' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned well as follows:

Plug #1 - 35 sacks Class C 2% CaCl₂ set at 3750'. Tagged cement at 3300, 450' of fill.
Plug #2 - 35 sacks Class C 2% CaCl₂ set at 2750'. Tagged cement in 2 hrs. No plug.
Plug #2 - 35 sacks Class C 2% CaCl₂ set at 2750'. Tagged cement in 2 hrs. Tagged at 2626'. Had 124' fill.
Plug #2 - 15 sacks Class C 2% CaCl₂ at 2626'. Tagged cement at 2316'.
Plug #3 - 25 sacks Class C 2% CaCl₂ at 2100'. Pulled out, no tags.
Plug #4 - 25 sacks Class C 2% CaCl₂ at 900'. Pulled out, no tags.
Plug #5 - 15 sacks Class C 2% CaCl₂ at surface.

Dry hole marker will be installed. Surface will be restored.
Verbal permission obtained from Mr. Bill Gressett, OCD, Artesia 11-24-81 for plugging.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Engineering Secretary	DATE 12-8-81
APPROVED BY <i>Danny Brooks</i>	TITLE <i>Geologist</i>	DATE 6-4-84
CONDITIONS OF APPROVAL, IF ANY:		