

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. IG-2678

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

7. Unit Agreement Name

Name of Operator

Cook Oil and Gas Production Co. ✓

AUG 19 1981

8. Farm or Lease Name

State

Address of Operator

P.O. Box 159, Roswell, New Mexico 88202-0159

O. C. D.

9. Well No.

#2-Y

ARTESIA, OFFICE

10. Field and Pool, or Wildcat

Shugart V-S&O-G

4. Location of Well

UNIT LETTER P 990 FEET FROM THE East LINE AND 960 FEET FROM

THE South LINE, SECTION 2 TOWNSHIP 19 S RANGE 31 E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3609.7

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

May 26, 1981

- 11:00 - 7:00 - Free point, trip out of hole, lay down fish, pick up 7 joints wash over pipe, trip in hole
- 7:00 - 3:00 - mixing pit of mud, circulated mud 1 hour, stud, wash pipe back in derricks
- 3:00 - 11:00 - run in hole, screw into fish bar free point, back of 18 DC, chain out, pick up, wash pipe, trip in DC

May 27, 1981

- 11:00 - 7:00 - trip hole with DP/mix mud/washing over collars
- 7:00 - 3:00 - washing down over collars to bit/circulate 1 hour/trip out hole/lay down over collars to bit/circulate 1 hour/lay down wash over pipe
- 3:00 - 9:30 - trip in hole/screw into trip out with fish
- 9:30 - 10:45 - trip in hole with bit #3
- 10:45 - 11:00 - wash to bottom

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

*Francis J. Cuchuleta*

TITLE

*Sec.*

DATE

*8/17/81*

APPROVED BY

*W. A. Gussert*

TITLE

*SUPERVISOR, DISTRICT II*

DATE

*AUG 19 1981*

CONDITIONS OF APPROVAL, IF ANY: