

C CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

|                                           |                              |
|-------------------------------------------|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br>IG-2678   |                              |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A WELL OR TO REPAIR OR MAINTAIN A WELL. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

AUG 19 1981

Name of Operator

Cook Oil and Gas Production Co. ✓

O. C. D.

Address of Operator

P.O. Box 159, Roswell, New Mexico 88202-0159

ARTESIA, OFFICE

7. Unit Agreement Name

8. Farm or Lease Name

State

9. Well No.

#2-Y

10. Field and Pool, or Wildcat

Shugart ✓ SR-Q-G

UNIT LETTER P 990 FEET FROM THE East LINE AND 960 FEET FROM

THE South LINE, SECTION 2 TOWNSHIP 19 S RANGE 31 E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3609.7

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

REPAIR OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

May 28, 1981 - 3038'

11:00 - 11:30 - Wash joint to bottom

11:30 - 7:00 - Drilling

7:00 - 3:00 - Drilling

3:00 - 11:00 - Drilling

May 29, 1981 3336'

11:00 - 6:30 - Drilling

6:30 - 7:00 - Trip out of hole

7:00 - 8:00 - Trip out for N Part

8:00 - 10:00 - Repair on rig/air comp and brakes

10:00 - 11:30 - Trip in hole

11:30 - 11:45 - Fill pipe/wash to bottom 32'/work on junk

11:45 - 3:00 - Drilling

3:00 - 11:00 - Drilling

May 30, 1981 3810' Dev 3/4"

11:00 - 7:00 - Drilling

7:00 - 3:00 - Drilling

3:00 - 11:00 - Drilling

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James B. O'Connell

TITLE Sec

DATE 8/17/81

APPROVED BY W.A. Gressitt

TITLE SUPERVISOR, DISTRICT II

DATE AUG 19 1981

CONDITIONS OF APPROVAL, IF ANY: