

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-23805

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG-6257

7. Lease Name or Unit Agreement Name

WILLIAMS STATE COM

8. Well No.

1

9. Pool name or Wildcat

ANGELL RANCH (BONE SPRING)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

SOUTHLAND ROYALTY COMPANY

3. Address of Operator

P.O. Box 51810, Midland, TX 79710-1810

4. Well Location

Unit Letter K : 1780' Feet From The SOUTH Line and 1980' Feet From The WEST Line

Section 2

Township 19S

Range 27E

NMPM EDDY

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/14/93: MIRU. BLEW DOWN WELL. NU WH. NU BOP. RLSD PKR. POOH W/TBG. RU WIRELINE. RIH W/CIBP SET AT 7550'.

10/17/93: RIH W/DUMP BAILER. DMPED 35' CMT ON TOP CIBP @ 7550'. ND BOP. WELDED ON PULL NIPPLE. CUT 4 1/2" CSG OFF AT 7000'. POOH W/50 JTS CSG.

10/18/93: POOH LD REST OF 4 1/2" CSG. NU BOP. RIH W/TBG TO 7050'

10/19/93: PMPED 35' CMT AT 7050'. POOH W/3000' TBG. WOC.

10/20/93: RIH W/TBG. TAGGED STUB PLUG AT 6930'. PU TO 5330'. PMPED 30 SXS CMT. PU TO 3215'. PMPED 30 SXS CMT. PU TO 2055'. PMPED 30 SXS CMT. WOC 4 HRS. TAGGED PLUG AT 2048'. PMPED 30 SXS CMT AT 2048'. PU TO 302'. PMPED 30 SXS CMT. POOH LD TBG. ND BOP. RIH TO 100'. PMPED 25 SXS SURFACE PLUG.

POOH. RDMO CUT OFF CSG 3' BELOW SURFACE. INSTALLED P & A MARKER.

LOCATION HAS NOT BEEN CLEANED AS OF THIS DATE. WILL FILE FOLLOW UP SUNDRY UPON COMPLETION OF CLEAN UP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE PRODUCTION ASSISTANT

DATE 10/25/93

TYPE OR PRINT NAME DONNA WILLIAMS

TELEPHONE NO. 915-688-6943

Blakem

Int Reg

9/28/93

*Post ID-2
12-10-93*

PKA