ENERG+	ANI	MINERALS	255	ARTH	VENT

	!	
DISTRIBUTION	Ī	!
BANTA FE	17	1
FILE	11	1
U.S.O.S.	1	
LAND OFFICE		
DEFRATOR	1	

OIL CONSERVATION DIVIS 1

DISTRIBUTION		DX 2088	Revised 10-1-
FILE	SANTA FE, NE	W MEXICO 87501	
U.S.O.S.			5a. Indicate Type of Leuse
LAND OFFICE			State Fee X
OPERATOR 1			5. State Of, & Gas Lease No.
	· ·		
SUN	DRY NOTICES AND REPORTS OF	N WELLS	
USE "APPL	ICATION FOR PERMIT -" (FORM C-101) FOR SU	UCH PROPOSALS.)	
I. OIL WELL WELL X	DYHER-	RECEIVED	7, Unit Agreement Name
2. Name of Operator		AUG 2 7 1981	8. Form or Lease Name
RALPH NTX /		MUG 2 7 1001	DEBBIE
3. Address of Operator		© . ¢. Đ.	9. Well No.
P.O. Box 617, Ar	tesia, New Mexico 882		#1
11M17 1 EYYER T .	660 PEET FROM THE East	1 NE AND 1980 FEET FRO	.Und. Cemetery Morrov
THE South LINE, SE	ETION 11 TOWNSHIP 20S	OUTDRANCE 24 East NAPA	
	15. Elevation (Show whether	DF, RT, GR, esc.)	12. County
	3608 GL		Eddy
16. Chec	k Appropriate Box To Indicate 1	Nature of Notice Report of O	<u>-</u>
	INTENTION TO:		T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL DE ALTER CABINE	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER Spudded & Set C	onductor Pipe X
OTHER	U		
17. Describe Proposed or Completed	Operations (Clearly state all pertinent det	ails, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.			
8/26/81			
	Set 39' of 20", 52.73#	Conductor Pipe with	2 1/2 yds. of,
	6 sx. mix per yard, ce	ment.	-
			•
•			
-			
	,		
8. I hereby certify that the information	on above is true and complete to the best of	I my knowledge and belief.	
/ VI	7	-	•
(Soll //	A		8/26/81
June 1 WX			u/a v / e /
	2	VALGORY BY GIVE TO THE COMPANY AND THE	
Way	Tresset III	PERVISOR, DISTRICT II	PATE SEP 1 1881