Submit 3 Copies to Appropriate District Office

State of New Mexico
gy, Minerals and Natural Resources Departme.

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION
P.O. Box 2088

WELL API NO.

DISTRICT II		Santa Fe, New Mexico 87504-2088		30-015-23931		
P.O. Drawer DD, Artesia, NM 88210	Santa re, New Mexic	0 67304-2066	5. Indicate Type	of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		and the second	6 0 0 0 0 0	STATE	FEE _	
1000 NO DIEZZE NU., PAZEC, 14191 67410			6. State Oil & Ga B-8096	is Lease No.		
SUNDRY NOTIC	ES AND REPORTS ON W	ELLS				
( DO NOT USE THIS FORM FOR PROP DIFFERENT RESERV (FORM C-10	OSALS TO DRILL OR TO DEEPE OIR. USE "APPLICATION FOR P D1) FOR SUCH PROPOSALS.)	HOR BLUG BACK TO A BRIMITO 1950	7. Lease Name of	Unit Agreement Name	:	
1. Type of Well: OIL GAS WELL K WELL	one OIL	CON. DIV.	Conoco 7	State		
2 Name of Operator SDX Resources, Inc.		nisī, 2	8. Well No.	8		
3. Address of Operator	TV 7070/		9. Pool name or V			
P. O. Box 5061, Midland, 7	1X /9/04		Millman,	QN-GR, East	- <u>-</u>	
Unit Letter B: 660	Feet From The North	Line and1880	Feet From	The East	1:-	
Section 7	100				Line	
Secucia .	Township 195 F	tange 29E N	MPM	Eddy <b>V</b> ////////////////////////////////////	County	
	3377' GR					
11. Check Ap	propriate Box to Indicate	Nature of Notice, Rep	cort, or Other	Data		
NOTICE OF INTE	NTION TO:	· ·		EPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS.	PLUG AND ABANDO	NMENT [	
PULL OR ALTER CASING		CASING TEST AND CEM	ENT JOB			
OTHER: Perfs in Queen 207	73-2144' X	OTHER:			Γ	
12. Describe Proposed or Completed Operation work) SEE RULE 1103.	s (Clearly state all pertinent details, a	nd give pertinent dates, includin	g estimated date of	starting any proposed		
Spudded 2/13/82. TD 2250						
	4-1/2" 6 total 21 holes, aci 20/40 & 10,000# 10/20		Frac w/	14,000 gals w		
	3,2431-2450',2401-242 0,000 gals & 42,000#			es), acidized	1 &	
	3,2227-2258',2199-221 0,000# 20/40 & 52,200 775 sxs.					
Plan to set RBP @ 2175' & perfs. Acidize all perfs Prep to start work 10/22/9	perf Queen 2073'2144 w/3000 gals of 15% M 6.	o', l spf. TIH w/ ISR acid. Will fr	pkr & spot ac if nece	acid across	a11	
I hereby certify that the information above is true and	complete to the best of my knowledge and	beliaf.				
SKONATURE Jamise (Od	utney m	Regulatory Te	ch	DATE10/17/	96	
TYPEOR PRINT NAME Janice Co	ourtney			915/685-1 TELEPHONE NO.	761	
(This space for State Use)						
ORIGINAL SIGN DISTRICT IS SUI	ed by tim W. Gum Pervisor			OCT 2	1996	
APPROVED BY		LE		DATE		