

Morris R. Antweil  
OIL OPERATOR  
P. O. Box 2010  
HOBBS, NEW MEXICO 88240

DEVIATION SUMMARY

Morris R. Antweil  
#1 Gulf Federal  
Section 31-T19S-R30E

Depth	Deviation
800'	1/2°
1310'	3°
1371'	2 3/4°
1660'	3°

A deviation summary was not provided by the drilling contractor, S & B Drilling Company. The above are all the deviations recorded on the daily drilling report forms. S & B Drilling Company can not be contacted. Apparently, they are not in business.

Sincerely,

MORRIS R. ANTWEIL



Jerry Hillard

:pb