

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

6.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such purposes.)

|                                                                                                                                         |  |                                                  |  |
|-----------------------------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                   |  | 5. LEASE DESIGNATION AND SERIAL NO.              |  |
| 2. NAME OF OPERATOR<br>Great Western Drilling Co.                                                                                       |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME             |  |
| 3. ADDRESS OF OPERATOR<br>O. C. D.<br>ARTESIA, OFFICE                                                                                   |  | 7. UNIT AGREEMENT NAME                           |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface |  | 8. FARM OR LEASE NAME                            |  |
| 14. PERMIT NO.                                                                                                                          |  | 9. WELL NO.                                      |  |
| 15. ELEVATIONS (Show whether DF, ST, OR, etc.)                                                                                          |  | 10. FIELD AND POOL, OR WILDCAT                   |  |
|                                                                                                                                         |  | 11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA |  |
|                                                                                                                                         |  | 12. COUNTY OR PARISH                             |  |
|                                                                                                                                         |  | 13. STATE                                        |  |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3/10/83: Finished running Pkr. to 11,858'. Broke circ. w/4 bbls. Pumped 250 gals. 10% acetic acid & spotted 120 gals., pulled 3 stds. tbg & set Pkr. @ 11,662'. Ran 1 11/16" tbg gun to 11,564' & could not go deeper. Worked gun w/no success. Retension Pkr without success. Ran sinker bars on sand line & hung up @ 9,500' w/1 13/16" OD, swab. P.O.H. & removed swab. Ran sinker bars only (1 3/4" OD) & got through tight spots & out of end of Pkr. Reran tbg gun & stopped @ 11,564'. P.O.H. & shut down.

3/11/83: Ran paraffin knife on sand line to top of Pkr. P.O.H. Ran sinker bars to 11,564' & couldn't get lower. P.O.H. Picked up on tbg to 2,000# Pkr. compression. Ran swab mandrel on sand line & worked through Pkr. 8-10 times - had drag each time. P.O.H. Ran tbg gun & stopped @ 11,564'. Picked up on tbg & was free - on & off tool was not engaged. Pulled tbg - marks on seal assembly indicated that assembly was not engaged. Pulled tbg - marks on seal assembly indicated that assembly was not engaged & was setting down on Pkr. off center. Tools & perforating gun had been stopping on top of packer. Ran 103 stds tbg w/packer releasing tool & shut down.

3/12/83: Ran 84 stds of tbg., caught & released Perma-Trieve Pkr. Lowered Pkr. to 11,984' & tagged W.A. Pkr - picked up 2' & reversed out acetic acid. P.O.H. & laid down Pkr. Ran Otis Perma-trieve Pkr on 2 3/8" N-80 tbg to 11,850' & left Pkr. swinging. Shut down - Perma-trieve Pkr. has on & off tool (Otis w/x profile). Left rubber & spring 1/4" x 8"

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL MAR 24 1983MINERALS MANAGEMENT SERVICE  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.