Form 9-331		INI. OLL COPIS. COMMISSION RAWER DD SUBMIT IN TRIPL - T	Form approved.
(May 1963) UN LD STATES SUBMIT IN TRIPL TE* DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY			Tre- 5. LEASE DESIGNATION AND SERIAL NO. LC-029392B
(The second state from the second	TICES AND REPO	an alway he als to a difference of the second se	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL CAS GAS WELL OTHER		AUG 23 1983	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Westall-Mask			8. FARM OF LEASE NAME Hinkle "B" Federal
3. ADDRESS OF OPERATOR P.O. Drawer 1477, Roswell, N.M. 88201		O. C. D. ARTESIA, OFFICE	9. WELL NO. #19
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10, FIELD AND FOOL, OR WILDCAT Shugart Y - 2 K - 2 11. SEC., T., R., M., OR BLK. AND
330' FWL and 990' FNL			SURVEY OR AREA 34-T18S-R31E
14. PERMIT NO.	15. ELEVATIONS (Show wh	hether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3618.9 GR		Eddy N.M.
		icate Nature of Notice, Report, or	
NOTICE OF INTENTION TO:		SUBS	EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	(Other)	ABANDONMENT
(Other)		(NOTE: Report resu	llts of multiple completion on Well mpletion Report and Log form.)
On August 19, 1983 th Ran 16 joints of 8 5/ 400 sacks Class C cen	'8" #20 pipe to 6 ment with 2% calc	57'	
Circulate 75 sacks ce	ment to the pit		RECEIVED Aug 19 2 53 PM 183 BUDDE CONSTRUCT
18. I hereby certify that the foregoing SIGNED Contract (This space for Federal ACSEAFED	2 Dudy TITL	Trustee for the Jack Mask Trust	DATE 8 13 83
APPROVED BY CONDITIONS OF APPROVAL, IF	CHESTER TITL	- .Æ	DATE
	*See Inst	ructions on Reverse Side	