COMMISSION UNITED STATES Drawer DD Artesia, HM 88010 GEOLOGICAL SURVEY SUBMIT IN TRACCATE* (Other instructions on re- verse side)				Form approved. Budget Bureau No. 42-B 5. LEASE DESIGNATION AND SERIAL LC-029392 B 6. IF INDIAN, ALLOTTEE OR TRIBE:	NO.
SUNDRY N	OTICES AND REPO	DRTS ON WELLS or pluREGE(V语的:rByrese	rvor.	6. IF INDIAN, ALLOTTEE OR TRIBE	SAME
(Do not use this form for proposals to drill or to deeper or plur to the proposals.) Use "APPLICATION FOR PERMIT—" for such proposals.) MAY 2.5 1984				7. UNIT AGREEMENT NAME	
WELL XX WELL OTH 2. NAME OF OPERATOR	ER			8. FARM OR LEASE NAME	
Westall - Mask V	· · · · · · · · · · · · · · · · · · ·	O. C. D. ARTESIA, OFFICE	1	Hinkle "B" Fede	ral
P.O. Drawer 1477 I 4. LOCATION OF WELL (Report local See also space 17 below.)	Roswell New Me	exico 88201 with any State requirements.		19 10. FIELD AND POOL, OR WILDCAT	
At surface 330' FWL and 990' FNL				Shugart Y- JR 9	Ž
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				Sec.34-T18S-R31	
14. FERMIT SO.	3618.9G			Eddy N.M.	
16. Check		dicate Nature of Notice, R	leport, or O		
				NT REPORT OF:	
nent to this work.) *	firectionally drilled, give subst	Completical pertinent details, and give pearface locations and measured an	CIDIZING Report results of the recompletion of Recompletinent dates, diruc vertical	ALTERING CASING ABANDONMENT* of multiple completion on Welltion Report and Log form.) ncluding estimated date of startic depths for all markers and zones	og any
We propose to do			1904		
We Propose to frac					
We propose to set		•			
Perferate 14 holes	s at 2' interva	als			
250 gallons acid					
40,000 gallons ge					
40,000# 20/40 sand			•		
Gyp control - (Tre	etolite)				
Frac down 4½ casing					
Original total de	pth 4200'				
	·				
18. I hereby certify that the foreg	d & bath m	TINTrustee of the	Jack Ma	ask Fryst 5-16-8	4
(This space for Federal or Sta	techno TI	ITLE P. E.		DATE 5-22-8	4_

MAY 2 3 1984 HOBBS OFFICE