

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-19442

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mason Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

N. Hackberry (Y SR) Est

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 33, T19S, R31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Santa Fe Exploration Company (505/623-2733)

3. ADDRESS OF OPERATOR

P. O. Box 1136, Roswell, NM 88202-1136

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

1980' FSL & 660' FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether at surface or depth)

3459.1 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

6-2-86 RU L&M Well Service. Load hole w/fr wtr.  
Set tbg @ 2390', cmt w/50 sx; WOC 2 hrs. Tagged cmt plug @ 2000'.  
Pulled tbg. RU Pengo Wireline, cut 5 1/2" csg @ top of cmt @ 980'.  
Load hole w/100 bbls 10# brine wtr & 10 sx salt gel.  
GIH w/tbg, set @ 1030'. Cmt w/25 sx; SDON.

6-3-86 Tagged cmt plug @ 868'.  
Set tbg @ 704', cmt w/35 sx; WOC 2 hrs. Tagged cmt plug @ 580'.  
Set tbg @ 280', cmt w/35 sx.  
Set tbg @ 62', cmt w/20 sx to surface.  
Installed Dry Hole Marker. RD L&M Well Service.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 6/5/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

Post FD-2  
10-17-86  
PFA