

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-015-24715

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
LG-1477

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Jack Plemons

3. Address of Operator  
P.O. Box 3225 Carlsbad, NM 88220

4. Well Location  
Unit Letter 0 : 990 Feet From The South Line and 1650 Feet From The East Line  
Section 3 Township 19s Range 31e NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:                        |                                                      | SUBSEQUENT REPORT OF:                               |                                                          |
|------------------------------------------------|------------------------------------------------------|-----------------------------------------------------|----------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>                 |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  |                                                      | CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                                          |
| OTHER: <input type="checkbox"/>                |                                                      | OTHER: <input type="checkbox"/>                     |                                                          |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Set CIBP @ 3312'
- 2.) Circ. hole wiith brine gell
- 3.) Spot 10 sxs "C" @ 3312-3212' on top of CIBP
- 4.) Spot 25 sxs "C" @ 2668-2418'
- 5.) Spot 25 sxs "C" + 3% Cacl2 @ 2282-2032' Tag @ 2067'
- 6.) Spot 35 sxs "C" + 3% Cacl2 @ 771-521' Tag @ 565'
- 7.) Spot 5 sxs "C" 30' to surface
- 8.) Install reg. marker

\* Notify N.M.O.C.D. to Witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William R. Hansen TITLE Agent DATE 04/23/98  
TYPE OR PRINT NAME William R. Hansen TELEPHONE NO 622-4772

(This space for State Use)

APPROVED BY maels wellfield TITLE Field Rep. II DATE MAY 12-98  
CO-SIGNATURES OF APPROVAL IF ANY: