

NM 28500

Hill Federal

1

Hackberry - Y - SR

S-21, T19S, R31E

Eddy

NM

3502. GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-21-84 Perforated: 2202-11 2 SPF-19 holes
2220-29 2 SPF-19 holes

6-22-84 Acidized: W/4,000 gal. SRA acid. Swabbed back. 10% oil cut.

6-25-84 Fracture: W/40,000 gal. lease oil, 60,000# 20/40, 10,000# 10/20 & flush. 40 BPM 2500# ISI 1600#

18. I hereby certify that the foregoing is true and correct

SIGNED

Ray Westall

TITLE

Operator

DATE

6-26-84

(This space for Federal use only)

ACCEPTED FOR RECORD

APPROVED BY

AWO

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

JUN 28 1984

*See Instructions on Reverse Side

NEW MEXICO