

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

95F
BIM Roswell District
Modified Form No.
NM060-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different level. Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. NAME OF OPERATOR Chevron U.S.A. Inc. ✓		3a. Area Code & Phone No. 505-393-4121	
3. ADDRESS OF OPERATOR P.O. Box 670, Hobbs, NM 88240		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1585' FSL and 925' FWL		5. LEASE DESIGNATION AND SERIAL NO. NM06766	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3248.3' GL		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N. Hackberry Yates Unit	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data				7. UNIT AGREEMENT NAME N. Hackberry Yates	
				8. FARM OR LEASE NAME Sec 24, T19S, R30E	
				9. WELL NO. 119	
				10. FIELD AND POOL, OR WILDCAT N. Hackberry Yates	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 24, T19S, R30E	
				12. COUNTY OR PARISH Eddy	
				13. STATE NM	

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
REPAIR WELL	☐	CHANGE PLANS	☐	(Other)	☐		
(Other)	☐			(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *							

MIRU PU, TIH W/2 3/8" WS OE TAG CMT @ 1716'
CIRC WELLBORE W/P&A MUD
SET CMT PLUG #1 FROM 1710 TO 1510 W/46 SX CMT
TAG TOC @ 1704' RT FOR SVCR SET SAME @ 1657 PMP 35 SX CMT ON TOP OF SVCR
TAG TOC @ 1305' SET SVCR @ 975' PMP 100 SX CL C CMT
STUNG OUT RETAINER LEAVING 20 SX CMT ON TOP OF RETAINER TAG TOC @ 902'
PUH TO 651' MIXED & PMPD 35 SX CL C CMT TAG TOC @ 435'
PUH TO 60' & CIRC CMT TO SURF
INSTALLED DRY HOLE MARKER
CHANGE WELL STATUS TO PLUGGED & ABANDONED

WORK STARTED 8-9-90 WORK ENDED 8-12-90

RECEIVED
AUG 17 11 47 AM '90
CARL
AREA
POST #D-2
8-31-90
PxA

18. I hereby certify that the foregoing is true and correct		
SIGNED <u>M. E. Abbin</u> 8/14/90	TITLE <u>Staff Drlg. Engr.</u>	DATE <u>8-15-90</u>
(This space for Federal or State office use)		
APPROVED BY <u>PETROLEUM ENGINEER</u>	TITLE <u>PETROLEUM ENGINEER</u>	DATE <u>8-23-90</u>
CONDITIONS OF APPROVAL, IF ANY:		

Approved for the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side