

C.L. CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

MAY 22 1985

O. C. D.
ARTESIA, NEW MEXICO

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-6852	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole - TA		7. Unit Agreement Name
Name of Operator		8. Farm or Lease Name
ARCO Oil and Gas Company, Division of Atlantic Richfield Company		State 2
Address of Operator		9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240		1
Location of Well		10. Field and Pool, or Whdcat
UNIT LETTER E 1855 FEET FROM THE North LINE AND 660 FEET FROM		Undesignated Bone Sprgs.
THE West LINE, SECTION 2 TOWNSHIP 19S RANGE 30E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3464.2' GR		Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Set CIBP <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to temporarily abandon and hold for further study in the following manner:

1. Rig up, install BOP and POH w/comp assy.
2. RIH w/CIBP. Set BP @ approx. 6950'.
3. Remove BOP, install gate on wellhead. Temporary abandon.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth L. Bush TITLE Dir. Eng. DATE 05/20/85

APPROVED BY ORIGINAL SIGNED BY LARRY BROOKS GEOLOGIST - NMCD TITLE DATE MAY 22 1985

CONDITIONS OF APPROVAL, IF ANY: