

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM DIST. CONS COMMISSION  
Dra DD  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <b>PLUGGED AND ABANDONED</b>	5. Lease Designation and Serial No. <b>NM-8673</b>
2. Name of Operator <b>YATES PETROLEUM CORPORATION (505) 748-1471</b>	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. <b>105 South 4th St., Artesia, NM 88210</b>	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., of Survey Description) <b>1830' FNL &amp; 660' FEL of Section 4-T19S-R30E (Unit H, SENE)</b>	8. Well Name and No. <b>Benson Deep FS Fed Com #1</b>
	9. API Well No. <b>30-015-25121</b>
	10. Field and Pool, or Exploratory Area <b>Benson Strawn Gas</b>
	11. County or Parish, State <b>Eddy Co., NM</b>

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

RECEIVED  
JUL 21 1995

Post ID-2  
8-4-95  
PFA

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5-31-95 - Moved in and rigged up pulling unit. TIH with 2-7/8" tubing to 10700'. Spotted 132 bbls plug mud from 10700-5000'. POOH with 2-7/8" tubing. Nippled down BOP and wellhead. Rigged up welder and welded 5-1/2" pull nipple. Picked up 5-1/2" casing to 527000#. Could not pull off slips. Heated slips and pulled on casing - slips would not move. Ran and cut 5-1/2" casing at 8500' with 4-1/2" jet cutter. Rigged down wireline. Rigged up pump. Pressured to 800#. Shut in overnight.

6-1-95 - Nippled up BOP. Released packer. POOH with tubing. Laid down packer. RIH with 5-1/2" CIBP and set at 10775'. Capped with 5 sacks of cement. Rigged down wireline. RIH with 2-7/8" tubing to 10000'. Shut in overnight.

6-2-95 - Rigged up wireline. Made 3 dump bailer runs. Dumped 15 sacks Class C cement from 8550-8450' in 5-1/2" casing. Ran and cut 5-1/2" casing at 6000' with 4-1/2" jet cutter. Rigged up pump. Pumped 220 bbls brine water. Got returns and shut in overnight.

6-3-5-95 - Rigged up welder. Cut 9-5/8" casing below wellhead. Picked up casing - casing not free. Pumped and worked casing. Rigged up welder. Cut wellhead off. Pumped and worked casing until casing stretched. Estimate free point at 3100'. Rigged up wireline. Ran and cut 5-1/2" casing at 5950' with 4-1/2" jet cutter. Rigged down wireline. Pumped and worked casing. Shut in overnight.

Approved as to plugging of the well bore  
Liability under bond is retained until  
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Rusty Klein Title Production Clerk Date June 16, 1995

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA Title PETROLEUM ENGINEER Date 7/19/95

Conditions of approval, if any: