

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

C157
Op

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OK CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-25181
Indicate Type of Lease STATE _____ FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Anderson Com
Well No. 1
Pool name or Wildcat Dagger Draw Strawn, East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL _____ WELL _____ GAS WELL <input checked="" type="checkbox"/> OTHER _____	
Name of Operator Nearburg Producing Company	
Address of Operator 3300 N A St., Bldg 2, Suite 120, Midland, TX 79705	
Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>20S</u> Range <u>25E</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3404' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Nearburg Producing Company has plugged and abandon the above referenced well.

Post P&A
2-15-02 MIRU service rig.
2-18-02 Set CIBP @ 9000' w/ 35 sx cmt on BP. Set 2nd CIBP at 8325' w/ 35' cmt on BP. Tagged TOC at 8285'.
2-19-02 Perforated 4 squeeze holes @ 6310'. TIH, set pkr at 6210', squeezed w/30 sx cmt.
2-19-02 Cut 4-1/2" csg @ 4850' and LD csg.
2-20-02 Spot 30 sx cmt plug f/ 4900' to 4800'. WOC. Tagged at 4785'.
2-20-02 Spot 40 sx cmt plug f/ 3050' to 2896'. WOC. Tagged at 2940'.
2-20-02 Spot 40 sx cmt plug 950' to 800'.
2-21-02 Spot 40 sx cmt plug f/ 400' to 300'.
2-21-02 Set surface plug.
2-23-02 Set dry hole marker. RDMO. Final Report.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Stewart TITLE Regulatory Analyst DATE 03-12-2002

TYPE OR PRINT NAME Kim Stewart

TELEPHONE NO. 915/686-8235

(This space for State Use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Wild SEP MAY 9 2002
DATE