

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 663622

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tenneco Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

N. Hackberry Yates 7-Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28, T19S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Cantro Exploration, Inc. ✓

3. ADDRESS OF OPERATOR

PO Box 700150, San Antonio, TX 78270 C.D.

AGENT: PO Box 196, Artesia, NM 88211

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

330' FNL & 1650' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3511' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(Other) ☐

Plug & Abandon

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to pump the following plugs to abandon the above captioned well. All plugs inside 5½" casing. The cement on the 5½" casing was circulated to surface when run.

Procedure I - pump 25 sx Class C cement from 2380' to 2148'. Allow to set and tag.

II - pump 5 sx Class C cement from 2038' to 1988'. Base Salt.

III - pump 5 sx Class C cement from 758' to 708'. Top Salt.

IV - pump 10 sx Class C cement from 250' to 350'. 50' below & above surface casing shoe.

V - pump 5 sx Class C cement to surface.

Dry hole marker will be installed and location will be restored and seeded. BLM will be notified prior to all work.

RECEIVED  
Aug 10 10 45 AM '88  
CARTER AREA

18. I hereby certify that the foregoing is true and correct

SIGNED

Martin Muncy  
for Robert Green

TITLE

Agent

DATE

8/8/88

(This space for Federal or State office use)

APPROVED BY

SEE RAJ GIRI

TITLE

DATE

8/31/88

CONDITIONS OF APPROVAL IF ANY SOURCES

\*See Instructions on Reverse Side