

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.E.	
LAND OFFICE	
OPERATOR	☒

OIL CONSERVATION DIVISION

RECEIVED BYO. BOX 2086
SANTA FE, NEW MEXICO 87501

DEC 12 1985

O. C. D.

ARTESIA OFFICE

Form C-103
Revised 10-1-73

1a. Indicate Type of Lease State ☐ Fee ☒
3. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Bogart
9. Well No. 1
10. Field and Pool, or Wildcat Und. Atoka Glorieta-Yeso
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator Chama Petroleum Company	8. Farm or Lease Name Bogart
3. Address of Operator P.O. Box 31405 Dallas, Texas 75231	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>19S</u> RANGE <u>26E</u> RMPM.	10. Field and Pool, or Wildcat Und. Atoka Glorieta-Yeso
15. Elevation (Show whether DF, RT, GR, etc.) 3363.1' GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER Activity ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

10/19/85:

RIH beside 8-5/8" csg. Tagged cmt at 400'. Mixed 50 sx 4% CaCl Class C cmt, wait 2 hrs. Tagged cmt at 400'. Mixed 50 sx 4% CaCl Class C cmt, wait 2 hrs. Tagged cmt at 270'. Mixed 50 sx 4% CaCl Class C cmt, wait 2 hrs. Tagged cmt at 225'. Mixed 50 sx 4% CaCl Class C cmt, wait 2 hrs. Tagged cmt at 200'. Mixed 50 sx 4% CaCl Class C cmt. Got NMOCD approval to dump 4 yds pea gravel in hole from 200' - 180', 20' fill. Circ. hole, got circ. Mixed 150 sx Class C 4% CaCl, SD WOC. WBIH and tagged cmt at 85'. Mixed 80 sx 4% Class C. Circ 5 sxs to pit. Cmt to surface. Wait 10 hrs. and cut off csg. Drlg to 4000'. Ran 95 jts. 5-1/2" 15.50# J-55 8rd csg. Set at 3988.26'. Cmt with 325 sxs Halliburton lite Class C, 8# salt/sx and 1.4# flocel/sx. Tailed in with 300 sxs Class C 50-50 poz, 2% gel, 1/4# flocel/sx, 3/10 of 1% Halad 4 and 5# salt/sx. Released plug, displace hole. Check float, holding. Circ. 18 sxs cmt to pits. Closed in well until completion.

10/20-27/85:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

W. H. Shelley, Jr. Swartzen Drubel

TITLE Regulatory & Production

DATE 12/11/85

Original Signed By

Les A. Clements

Supervisor District 11

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

DATE DEC 23 1985