orm 3160-5 dovember 1983) Formerly 9-331) DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEMEN	OR verse side)	Budget Bureau No. 1004-0135 Expires August 31, 1985 6. LEASE DESIGNATION AND SERIAL NO. NM-025777
SUNDRY NOTICES AND REPORTS (Do not use this form for proposals to drill or to deepen or plus use "APPLICATION FOR PERMIT—" for such	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
AU 50 644 50	RECEIVED BY	7. UNIT AGREEMBNY NAME
WELL X WELL OTHER	MAR 18 1986	S. PARM OR LEASE NAME
Siete Oil and Gas Corporation	O. C. D.	Geronimo Federal 9. WBLL NO.
- 0500 D		#5 10. FIELD AND POOL, OR WILDCAT
P. O. Box 2523, ROSWEIL, NM 66201 Location of Well (Report location clearly and in accordance with an See also space 17 below.) At surface		Wildcat - Wolfcamp
765' FNL & 1980' FEL, NW/4 NE/4, Unit	letter B	SURVEY OR ARMA
14 PERMIT WO 15. SLEVATIONS (Show whether	DV ST CR. etc.)	Sec. 24: T18S, R31E 12. COURTY OR PARISE 18. STATE
14. PERMIT NO. 15. ELEVATIONS (Show whether 3717 °GR		Eddy NM
Check Appropriate Box To Indicate		
NOTICE OF INTENTION TO:	8088	AQUANT REPORT OF:
PEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all perting the proposed of the perting of the p	Completion or Reco	nits of multiple completion on Well impletion Report and Log form.)
3/13/86 - T.D 10200' - Rig u 4 (150') plugs as follows: #1 09' out of shoe 05350' - plug back - - BLM Carlsbad - tag plug #4 w/dril p.m.	790' - #2 @8203' - verbal approval obta	#3 06400' - #4 in and ained from Bob Pischke
He.	FOR RECORD / 17 1986	
CARLSBAD,	NEW MEXICO	
(This space for Federal or State office use)	Vice President	DATE3/14/86
PROVED BYTITLE _		DATE