

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐		RECEIVED OCT - 6 1986 O. C. D. ARTESIA, OFFICE	
2. NAME OF OPERATOR Harvey E. Yates Company			
3. ADDRESS OF OPERATOR P.O. Box 1933 Roswell, New Mexico 88201			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FSL & 990' FEL			
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3716 GL	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		17. COUNTY OR PARISH Eddy	
18. STATE N.M.		19. WELL NO. 1	
20. FIELD AND POOL, OR WILDCAT Wildcat-Delaware		21. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 13, T18S R31E	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
- | NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|-------------------------|--------------------------|-----------------------|-------------------------------------|
| TEST WATER SHUT-OFF | ☐ | WATER SHUT-OFF | ☐ |
| FRACTURE TREAT | ☐ | FRACTURE TREATMENT | ☐ |
| SHOOT OR ACIDIZE | ☐ | SHOOTING OR ACIDIZING | ☐ |
| REPAIR WELL | ☐ | (Other) | ☐ |
| PULL OR ALTER CASING | ☐ | REPAIRING WELL | ☐ |
| MULTIPLE COMPLETE | ☐ | ALTERING CASING | ☐ |
| ABANDON* | ☐ | ABANDONMENT* | ☐ |
| CHANGE PLANS | ☐ | Completion | ☒ |
- (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *
- 8-7-86 Perf @ 5059-68 Acidize w/ 2000 Gal 15% & frac w/ 20,000 Gal WF3PSD & 28,000# 20/40. Swab test.
 - 8-14-86 Squeeze perfs 5059-68 w/200 sks class 'A' cement.
 - 8-21-86 Perf @ 5119 w/4 holes & squeeze w/600 sks class 'A'
 - 8-24-86 Perf @ 5182-5210. Acidize w/2500 Gal 15% & frac w/20,000 Gal of WF3PSD & 5000# 100 Mesh & 28,000# 20/40 Swab test.
 - 9-3-86 Set RBP @ 5085 Perf @ 5063. Acidize w/500 Gal 15%
 - 9-5-86 Frac w/ 20,000 Gal WF3PSD & 8000# 100 Mesh & 30,000# 20/40 Sand. Swab test.
 - 9-10-86 Put well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED H. M. Young N.M. Young TITLE Drilling Superintendent DATE 9-26-86

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD
DATE 10/3/86

OCT 03 1986

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO