

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Artesia, NM 88210

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. NAME OF OPERATOR Siete Oil & Gas Corporation		RECEIVED BY JUL 28 1986 O. C. D. ARTESIA, OFFICE	5. LEASE DESIGNATION AND SERIAL NO. LC-065680	
2. ADDRESS OF OPERATOR P. O. Box 2523, Roswell, NM 88201			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FSL & 990' FWL, SW/4 SW/4, Unit Letter M			7. UNIT AGREEMENT NAME	
4. PERMIT NO.			8. FARM OR LEASE NAME Blackhawk Federal	
9. ELEVATIONS (Show whether DV, HT, GR, etc.) 3694' GR		9. WELL NO. 4		10. FIELD AND POOL, OR WILDCAT Shugart
11. SEC. T., R., M., OR B.L. AND SURVEY OR AREA Sec. 24: T18S, R31E		12. COUNTY OR PARISH Eddy		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACURE TREAT	<input type="checkbox"/>	FRACURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other) Plug & Abandon	<input checked="" type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/20/86 - Instructions & verbal approval per Bob Pitschke - Spot 35 sxs - plug @4500' - back to 4400' - plug #2 3750' to 3650' - plug #3 2200' to 2100' - will wait 2 hrs. tag top of cement @2085' - plug #4 950' to 850' - plug #5 400' to 300' in & out of shoe - plug #6 50' @surface - release L & M Rig #1.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Vice President</u>	DATE <u>7/17/86</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>MANAGER</u>	DATE <u>7-23-86</u>
CONDITIONS OF APPROVAL, IF ANY:		

\*See Instructions on Reverse Side