

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

EXPIRES AUGUST 31, 1983
5. LEASE DESIGNATION AND SERIAL

LC-065680

6 IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR Siete Oil & Gas Corporation
3. ADDRESS OF OPERATOR P.O. Box 2523 Roswell, NM 88202-2523
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 2310' FSL & 330' FEL, NE 1/4 SE 1/4, Unit Letter I
14. PERMIT NO. 30-015-25651 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3696' GR
O.C.D. ARTESIA, OFFICE

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Blackhawk Federal
9. WELL NO. 5
10. FIELD AND POOL OR WILDCAT Shugart Penrose
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 23: T18S, R31E
12. COUNTY OR PARISH Eddy 13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1/23/89 RU Schlumberger & perfed 3713'-3734' w/15 perforations, TIH w/RBP and set @ 3776', circ hole clean w/2% KCl, TIH w/tbg, set @ 3734', spot 2 bbls over perfs, pulled tbg to 3571', formation broke @ 1200, acidized w/1000 gal 15% HCl, AIR-3 1/2 BPM, AIP-1700, balled out @ 3000, finish flush @ # BPM @ 1590, ISIP-1080, @ 5 min-920, @ 10 min-840, @ 15 min-770, SION.
- 1/24/89 RU Western Co. & fraced w/31,000 gal 20# XL, 2000# 100 mesh, 30,000# 20/40 & 20,000# 12/20, AIR-20.2 BPM, AIP-1950, max-2300, min-1800, ISIP-1900, @ 5 min-1650, @ 10 min-1600, @ 15 min-1500, SION.
- 1/25/89 Circ sand out of hole and began swabbing.

18. I hereby certify that the foregoing is true and correct

SIGNED

Cathy J. Batley

TITLE Drilling & Production

DATE 1/26/89

(This space for Federal or State office use)

APPROVED BY

TITLE

ACCEPTED FOR RECORD

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 8 1989

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO