

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT INSTRUMENT  
(Other instructions on re-  
verse side)

EXP. DATE 1-1-88  
5. LEASE DESIGNATION AND SERIAL

LC 029389 (A)

c/5F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Baish Federal

9. WELL NO.

3

10. FIELD AND POOL OR WILDCAT

N. Shugart Bone Springs

11. SEC., T., R., M., OR BLE. AND  
SURVEY OR AREA

9-18S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

ARCO Oil and Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 1610, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below)  
At surface

RECEIVED BY

MAY -1 1987

O.C.D.  
ARTESIAL OFFICE

660' FNL & 1980' FWL (Unit Letter C)

14. PERMIT NO

30-015-25729

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3713.6

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

Spud, Surf Csg, Int Csg

NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Check or state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spud 9:00 am 4-9-87. TD'd 17-1/2" hole @ 685'. Run 13-3/8", 54.5# csg & cmt'd at 685' w/900 sx "H" Neat. Circ cmt to surf. WOC. Press test to 1000#. TD'd 11" hole at 2162'. Run 53 jts 8-5/8", 24#, J-55 csg. Cmt'd @ 2162' w/750 sx "H" LW to followed by 250 sx "H" Neat. Did not circ cmt. WOC. Run temp survey TOS @ 180'. Press test to 1000#. Drld ahead w/7-7/8" bit.

PUMPED 30 SXS TO CIRC. (SJS)

ACCEPTED FOR RECORD

SJS

APR 27 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Ken W. Hosnell

TITLE

Engr. Tech. Spec.

DATE

4-15-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side