

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

ON WELL ☒ GAS WELL ☐ OTHER ☐

4. NAME OF OPERATOR

Siete Oil & Gas Corporation

5. ADDRESS OF OPERATOR

P. O. Box 2523, Roswell, NM 88201

6. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2310' FSL, 1650' FEL, NW/4 SE/4, Unit Letter J

10. PERMIT NO.

11. ELEVATIONS (Show whether SF, ST, GR, etc.)

3700' GR

RECEIVED BY

MAR 5 1987

O. C. D.

ARTESIA, OFFICE

7. LEASE DESIGNATION AND SERIAL NO.

NM-025777

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

9. UNIT AGREEMENT NAME

10. NAME OR LEASE NAME

Geronimo Federal

11. WELL NO.

10

12. FIELD AND POOL, OR WILDCAT

East Shugart Delaware

13. SEC., T., R., N. OR BLM. AND
SURVEY OR AREA

Sec. 24: T18S, R31E

14. COUNTY OR PARISH

Eddy

15. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Spud & set surface casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

3/02/87 - L & M Rig #1 spudded 12 1/4" hole w/Bit #1 12 1/4" Security F44 @8:00
a.m. - notified BLM (A.W. Nelson) @8:15 a.m. - L & M Rig #1 - T.D. 12 1/4"
hole to 351' @1:15 p.m. - started out of hole w/DP - stuck DP in red bed
- install jars - jarred pipe loose @5:00 p.m. - lay down jars & collars
- ran 8 jnts 8 5/8" 23# J-55 csg + landing jnt (352.4') csg set @350'KB
- RU Dowell Schlumberger & cmt'd w/230 sxs Hi Early II, 2# CaCl₂, 1/4# celloflake
- circ 25 sxs to pit - dev survey: 1/2° @351' - PD @7:15 p.m. - W.O.C. 5
hrs

3/03/87 - W.O.C. 13 hrs - Test BOP to 1000 PSI for 30 minutes held OK.

18. I hereby certify that the foregoing is true and correct

SIGNED

A.D. Gustaf

TITLE V.P. Drilling & Production

DATE 3/03/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 03 1987

CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side