

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
(Other Instructions on Form 1001)

Revised August 26, 1983

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER

DEC 04 '87

1. NAME OF OPERATOR

Siete Oil & Gas Corporation

O. C. D.

2. ADDRESS OF OPERATOR

P. O. Box 2523 Roswell, New Mexico 88202

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2310' FSL & 1650' FEL NW/4 SE/4

4. PERMIT NO.

API-30-015-25735

5. ELEVATIONS (Show whether by, to, or etc.)

3678' GR

6. LAND DESIGNATION AND AGENCY NO.

LC-065680

7. IF APPLICABLE, ALLOTTEE OR TRUST NAME

8. UNIT ABBREVIATION NAME

9. NAME OF LAND NAME

Blackhawk Federal 10145

10. WELL NO.

6

11. TOWN AND RANGE, OR WILDCAT

Shugart V-3K-9 San Andres

12. SEC. T. R. M., OR BLM, AND SURVEY OR AREA

Sec. 23: T18S R31E

13. COUNTY OR PARISH

Eddy

14. STATE

NM

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FILL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug and Abandon

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

16. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface location and measured and true vertical depths for all markers and zones pertinent to this work.)

11/24/87

1. Set cast iron bridge plug @ 4200'

2. Set 35' cement plug on top of CIBP

3. Set 100' cement plug from 300' to 400'; Across 8 5/8" shoe

4. Set 50' cement plug in 5 1/2" casing @ surface
10#/gallon salt gel mud used between plugs.

5. Set 4' marker w/legal description welded on @ surface.

17. I hereby certify that the foregoing is true and correct

SIGNED

H. D. Justice

TITLE

V. P. Drilling and Production

DATE

Nov. 25, 1987

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Liability under bond is retained until
various restrictions are lifted

*See Instructions on Reverse Side