

dsr

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

5. Lease Designation and Serial No.
NM 29826

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Walters Federal

9. API Well No.
1

10. Field and Pool, or Exploratory Area
Undes McMillan V. Penn

11. County or Parish, State
Eddy Co. N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Robert N. Enfield

3. Address and Telephone No.
P.O. Box 2431 Sante Fe, New Mexico 87501 (505)988-2863

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980 FNL 990 FEL
Sect. 7 T-19-S R-27-E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Set 4-1/2" Cast Iron Bridge Plug at 7830' and cap with 5 sacks of cement.
- 2) Load hole with brine gel mud.
- 3) Cut 4-1/2" casing at 5017' and pull out of hole.
- 4) Spot 35 sacks cement plug at 4-1/2" stub 5127' W.O.C. Tag at 4901'.
- 5) Spot 60 sacks cement Plug at 4000'.
- 6) Spot 70 sacks cement plug at 2500' W.O.C. Tag at 2287'.
- 7) Spot 132 sacks cement plug from 450' to surface
Set P & A marker up. 10-28-92

Post ID-2
12-18-92
P&A

P&A on 10-8-92.

14. I hereby certify that the foregoing is true and correct

Signed Raymond M. Edwards Title Supervisor Date 10-13-92

(This space for Federal or State office use)

Approved by _____ Title _____ Date 12-10-92

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.