

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-25863

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

013550

7. Lease Name or Unit Agreement Name

Anderson 15

8. Well No.

#1

9. Pool name or Wildcat

Cemetery Morrow

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Nearburg Producing Company

3. Address of Operator

P. O. Box 823085, Dallas, TX 75382-3085

4. Well Location

Unit Letter H : 1,755 Feet From The North Line and 660 Feet From The East Line

Section 15

Township 20S

Range 25E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3,430.9' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU plugging unit. Set CIBP @ 9,446' w/15 sx cement.

2. Circ hole w/25#/bbl gel mud.

3. PU csg and cut @ 7,003' at free point and LD.

4. Pump 50 sx Premium Plus cement from 7,050' to 6,650'. (4-1/2" csg stub).

5. WOC for 3 hrs. TIH and tag TOC @ 6,877'. Witnessed by OCD.

6. Pump 30 sx Premium Plus cement from 4,675' to 4,575'.

7. Pump 30 sx Premium Plus cement from 2,575' to 2,475'.

8. Pump 60 sx Premium Plus cement from 1,450' to 1,255'. Tag hole.

9. Pump 30 sx Premium Plus cement from 488' to 300'.

10. Surface plug w/10 sx Premium Plus cement. Set dry hole marker.

RECEIVED

MAY 19 1995

OIL CON. DIV.
DIST. 2

Pat ID-2
6-9-95
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Drilling Supt.

DATE May 17, 1995

TYPE OR PRINT NAME

H. R. Willis

TELEPHONE NO. 505/397-4186

(This space for State Use)

APPROVED BY

TITLE

Field Rep

DATE

6-22-95

CONDITIONS OF APPROVAL, IF ANY: