Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

CONDITIONS OF APPROVAL, IF ANY:

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.
P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088		30-015-25885	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. 013545
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Anderson 11 £
1. Type of Well: OIL GAS WELL X	OTHER	V	
2. Name of Operator			8. Well No.
Nearburg Producing Company			#1
3. Address of Operator			9. Pool name or Wildcat
P. O. Box 823085, Dallas, TX 75382-3085			Cemetary Morrow
4. Well Location			
Unit Letter <u>E</u> : <u>1,98</u>	80 Feet From The North	Line and33	O Feet From The West Line
	000	OER	Edda a
Section 11	Township 20S Ra		NMPM Eddy County
	/////	Dr., raid, Mr., Ori, e.e.,	<i>\(\(\(\(\(\(\(\(\(\(\)\\\\\\\\\\\\\\\\</i>
	Annoniota Dan ta Indianta	Matura of Matica D	aport or Other Data
	Appropriate Box to Indicate 1		
NOTICE OF IN	TENTION TO:	SUB	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
۲	CHANGE FLANS		
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB []
OTHER:		OTHER:	
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	ntions (Clearly state all pertinent details, ar	nd give pertinent dates, inclu	ding estimated date of starting any proposed
 MIRU plugging un witnessed.) 	nit. Set CIBP @ 9,327'	w/10 sx cement	. (Mike Stubblefield w/OCD
2. Fill hole w/25#,	bbl gel mud.	017! + 7 700!	
3. Pump 25 sx Prem:	ium Plus cement from 7,	017 to 7,700 .	MAY 1 9 1995
6. PU csg and cut (ium Plus cement from 1.	740' to 1.640'.	(4-QIL-CQM, DIV.
7. Pump 60 sx Prem: 8. WOC for 3 hrs.	TIH and tag TOC @ 1.67	O' (witnessed b	oy OCD rep). DIST 2
9. Pump 50 sx Prem	ium Plus cement from 1,	410' to 1,310'.	oy OCD rep). DIST. 2 Tag TOC @ 1,285' (witnessed
by OCD rep).			PotIDo
10. Pump 30 sx Prem	ium Plus cement from 42	0' to 320'.	Prof FD 2 6-9-95
11. Surface plug w/	10 sx Premium Plus ceme	nt. Set dry ho	ole marker.
			1797
I hereby cerufy that the information above is fru	e and complete to the best of my knowledge and		
SIGNATURE) ller m	LEDrilling	g Supt. May 17, 1995
TYPE OR PRINT NAME H. R. WI	llis		TELEPHONE NO. 505/397-418
(This space for State Use)			
Man 7	1 rem Millon	Field R.	pare 6-22-95
APPROVED BY	т	TE	DATE