## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HGY AND MINCHALS DE		
WO. OF COPIES ACCEIVED	<u> </u>	
DISTRIBUTION		_
SANTA FE	V	
FILE	V	1
U.S.G.S.		<del>     </del>
LAND OFFICE		
OPERATOR	V	

## OIL CONSERVATION DIVISION

	OIL CONSERVATIO	אטופועוט אן	r c 102
us. or corics acceives			Form C-103 Revised 10-1-78
DISTRIBUTION	P. O. BOX 208: SANTA FE, NEW MEX	CICO 87507 LIVED	
SANTA FE	<b>5</b>		5a. Indicate Type of Lease
7168			State Fee X
U.S.G.S.		SEP 27 '88	5. State Oil & Gas Lease No.
LAND OFFICE		OLI EI OO	
OPERATOR V			mmmmmm
CHURDY NO.	TICES AND REPORTS ON WELL	LS C, C. D.	
(DO NOT USE THIS FORM FOR PROPOSALS	TO DRILL OR TO DEEPEN OR PLUG BACK TO PERMIT -" (FORM C-101) FOR SUCH PROP	SALS.)	
(DO NOT USE "APPLICATION FOR	PERMIT - FORM C-1011		7. Unit Agreement Name
1.			
OIL GAS WELL X OT	HER+		8. Farm or Lease Name
2. Name of Operator			Parino 23L
Nearburg Producing Cor	npany		9. Well No.
1.0 - sector			2
P.O. Box 31405, Dalla:	s, Texas 75231		10. Field and Pool, or Wildcat
			i i
4. Location of Well  UNIT LETTER L	Most	1500 FEET FROM	Boyd Morrow
L 1200	FEET FROM THE WEST LI	NE AND	
	100	250	
THE South LINE, SECTION	23 TOWNSHIP	RANGE ZJE HMPM	
THE			12. County
Tillini minimini minimi	15. Elevation (Show whether DF, I	RT, GR, etc.)	
	3433.3 GR.		Eddy (1111111)
	opriate Box To Indicate Natur	e of Notice. Report or Ot	her Data
16. Check Appre	opriate Box To Indicate Natu	SUBSPOLLEN	T REPORT OF:
NOTICE OF INTEN	ITION TO:	30032402.	
		$\Box$	ALTERING CASING
	PEGG XNO NONNE	MEDIAL WORK	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	con	MMENCE DRILLING OPNS.	PLUG AND ABARDONMENT
TEMPORARILY ABANDON		SING TEST AND CEMENT JOB	
PULL OR ALTER CASING	CHARGE TOWN	OTHER	

- 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1 103.
  - Spud @ 1:00 PM (MST). Drilled  $17\frac{1}{2}$ " hole to 350'. Reduced hole size 7-13-88 to  $12\frac{1}{4}$ , drilled to 1375'.
  - Ran 32 joints 8 5/8", 24# casing set @ 1373'. Cemented with 1,000 SX. Hal. Lite 1,000 Gal, Flo-check 21, 1/4 Flocele per sack and 2% CaC1. 7-15-88 Tailed in with 200 sacks premium plus and 2% CaCl. Plug down @ 11:35 PM, 7-15-88. Circulated 135 sacks to Pit. Held 1,000 PSI for 30 miniutes. WOC 18 hours. Drilled 7 7/8" hole to 9600'. Ran logs.
  - Ran 247 joints  $4\frac{1}{2}$ ", 11.60# casing set @ 9595. Cemented with 750 sacks

8-07-88	Ran 247 joints 42, 11 Premium Plus, 3% CFR, 6 Ran temperater survey,	and 4% Halid 22A. Plug down top of cement 7100' outside	@ 8:00 AM, 8-7-88. 4½".
18. I hereby certify	that the information above is true and complet	e to the best of my knowledge and belief.  Operations Coordinator	DATE 9-16-88
BIGHED GA	Original Signed By Mike Williams	TITLE	SEP 2 0 1988
CONDITIONS OF	APPROVAL, IF ANY:		

RECEIVED

SEP 26 1988

OCD HOBBS OFFICE