5	IAIL UI	INLAA	101-2-1
ENERGY	AND MIN	ERALS	DEPARTMEN

EHGT AND WINVEHALS D	<u> </u>	
MB. OF COPICS ACCCIVES		
DISTRIBUTION		<u></u>
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		·

OIL CONSERVATION DIVIS NEIVED P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103 Revised 10-1-78

SANTA FE		S	ANTA FE, N	1EM	MEXICO 87501		
FILE	VV				NOV O / 200		Indicate Type of Lease
U.S.G.S.					NOV 04 '88		State Fee X
LAND OFFICE						5.	State Oil & Gas Lease No.
OPERATOR					©, C. D.	1	
					ARTESIA, OFFIC	- /	THITTITITITI
	CHMDD	Y NOTICES A	ND REPORT	S ON V	VELUS	. <i>[]]</i>	
100 HOT USE	SUNUK THIS FORM FOR PRO- USE "APPLICATI	POSALS TO DRILL	OR TO DEEPEN OR	PLUG BA	CK TO A DIFFERENT RESERVOIR.		
(00 1101 001	USE "APPLICATI	ON FOR PERMIT -	Tronm Citotri			7.	Unit Agreement Name
1.	cas [33]						
WELL	WELL X	OTHER-				8.	Farm or Lease Name
2. Name of Operator						1	PARINO 23L
NEA!	RBURG PRODUC	ING COMPAN	1Λ ∧				Well No.
3. Address of Operato						9.	2
3. Address of Obergin	Box 31405	DALLAS.	TEXAS 7523	31			_
	. DOX 31403					10	. Field and Pool, or Wildcat
4. Location of Well					1500	1	BOYD MORROW
	Τ.	1.200 FEET	FROM THEY	VEST_	LINE AND 1500 FEET	FROM T	
		23		195	RANGE	кмрм. 🚺	
THESOU'I'	H LINE, SECTION	JNZ_	TOWNSHIP				<i>1111111111111111111111111111111111111</i>
		mm	Show w	hether	DF, RT, GR, etc.)	1:	2. County
		'////// 13. ₅				1	EDDA (11111111)
		/////	34.	<u>33.3</u>	_GR		
16.	Chaple	Appropriate !	Box To Indic	ate N	ature of Notice, Report of	or Other	Data
	Check	Who have a	0.		SUBSEQ	UENT R	EPORT OF:
	NOTICE OF I	TENTION I	J:				
						7	ALTERING CASING
PERFORM REMEDIAL	WORK		PLUG AND ABANDO	» []	REMEDIAL WORK	า	PLUG AND ABANDONMENT
	1 1				COMMENCE DRILLING OPHS.	4	
TEMPORARILY ABAND			CHANGE PLANS		CASING TEST AND CEMENT JOB		X
PULL OR ALTER CASI	NG				OTHERACTIVITY		
OTHER							7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
		-tions (Clear)	v state all pertit	ent det	ails, and give pertinent dates, inc	cluding es	timated date of starting any proposec
17. Describe Propos work) SEE RUL	sed or Completed C	perations (Crears	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
WOLK) SEE HOL							_
					BOP'S. PICKED UP 3	7,000	π AND $4^{1}/2$ CASING
10-3-88:	PICCED IIP (OMPLETION	RIG. INSTA	LLED	BOP'S. PICKED UP 3	\o BT.	r AND 4 /2 Closice
10-3-00:	SCRAPPER.	DAN IN F	OLE TO PBI	D 95	12'.		
				c	15% HCL. CIRCULATED I	HOLE C	LEAN. LOADED HOLE
10-4-88:	ACID WASHEL) INBING MI	TH 400 GAL	ν., 	RIP OUT OF HOLE WITH	BTT &	SCRAPPER.
	WITH 150	bbls OF 28	5 KCL WATER	(. T	RIP OUR OF HOLL WITH	<i>D</i> 11 -	
							0 61 9268-70
10 E 00.	DANI VANNI SI	HTTW METERS	OTIS PERM	TAJ-	CH PACKER. PERFORAT	ED 920	0=01, 3200 70,
10-2-00:	CAN VANCE D.	2 SHOTS PE	P FOOT S	SLIGH	T GAS BLOW		
	9219-04	2. 311013 11	M 10011			1	
			TOTAL TITUE!	2 000	GAL MORROW FLOW BC	7 ¹ /2%	ACID, 40 BALL
10-6-88:	RELEASED G	JNS. ACID	IZED WITH	2,000	CAL PORTON 12011 TO CI	EVM IIE	
		-710 T'000 T			=: •		
			20		AND FOAM GEL. FLOWI		r mo CIENN IID
40 40 00	EDACED MET	ר הודיים או י	500# ²⁰ /40 ⁽	SAND	AND FOAM GEL. FLOWI	NG WEI	T TO CLEAN OF
10-13-88:	FRACED WELL	L WITH 20,	JOON 7 20 1				
			N. T.IT)				
10-14-88:	FLOWING WE	LL TO CLEA	N OP				
10_15_88	FLOWING WE	LL TO CLEA	N UP				
	that the informati	on above is true	and complete to	the bes	t of my knowledge and belief.		
18. I hereby centil	y milet the shear a						
P	\cap ℓ	'0.1/	/	(PERATIONS COORDINATO)R	DATE 11/2/88
Edd	lio XX	eluis	T1	TLE	JI BRUIT TOTAL		
* ICHEC			- I D.				4000
		Original S	igned by				NOV 8 1988
		Mike V	Villiams ,	T L E			DATE
A P+RDY(D BY							
CONCITIONS OF	APPROVAL, IF A	47:					