

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT" for such proposals.)

LC-029387-D

75F

ON ☒ WELL ☐ GAS WELL ☐ OTHER

NAME OF OPERATOR

Siete Oil & Gas Corporation

ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

RECEIVED

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
(See also space 17 below.)
At surface

990' FSL & 660' FWL, Unit Letter M, SW $\frac{1}{4}$ SW $\frac{1}{4}$

JUL 19 '89

O. C. D.

10. PHONE NO

30-015-25966

11. ELEVATIONS (Show whether OF, ON, OR IN)

3561' GR

ARTESIA, OFFICE

12. COUNTY OR PARISH

Eddy

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PILL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completions on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface latitudes and measured and true vertical depths for all markers and given pertinent to this work.)

9/27/88 TIH w/tbg, set retainer @ 3695', squeezed w/300 sks class C, 2% S-1, tail-in w/100 sks class C neat, AIR-2 3/4 BPM, AIP-900, FPIP-1230, sting out of tool, reserve circ cement, TOH w/tbg, prep to perf 3639'-3648' & acidize.

9/28/88 RU Schlumberger & perfed as follows: 3639', 3640', 3641', 3642', 3643', 3644', 3645', 3646', 3647' & 3648' w/1 JSPF (total 10 perforations), TIH w/pkr & tbg, spot 1 1/2 bbls over perfs, set pkr @ 3593', formation broke @ 2280 PSI, acidize w/100 gal 15% HCl, dropped 20 ballsealers, AIR-3.5 BPM, AIP-2200, balled out to 4800, FPIP-2230 PSI, ISIP-1600 PSI, @ 5 min-1560, @ 10 min-1540, @ 15 min-1540, swab load back, trace oil, no gas, swab from SN, fluid entry, 1000'/30 min.

9/29/88 TP-220, FL @ surface, swab dry, continue swabbing, SD 30 min between swab runs, RD pulling unit, open well up to frac tank.

CONFIDENTIAL

OCT 3 11 03 AM '88

OCT 3 11 03 AM '88

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

Cathy Botley

TITLE

Drilling/Production Secretary

DATE

9/30/88

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

OCT 1 7 1988

SJS

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO