

SUNDRY NOTICES AND REPORTS ON WELLS 88210

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
See "APPLICATION FOR PERMIT" for such proposals.)WELL ☒ NEW ☐ OTHER

NAME OF OPERATOR

Siete Oil & Gas Corporation

ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

RECEIVED

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

At surface

1980' FNL & 1980' FWL, SE $\frac{1}{4}$ NW $\frac{1}{4}$, Unit Letter F OCT 19 '88

O. C. D.

PHONE NO

30-015-25985

ELEVATIONS (Show whether SP, ST, OR, OR)

3313' GL

ARTESIA, OFFICE

1. DATE OF REPORT

2. NAME OF LAND OWNER

Renegade Federal

3. WELL NO.

1

4. ROAD AND POOL, OR TRACT

Parkway Delaware

5. SEC. T. R. IN. OR BLM. AND
COUNT ON AREA

Sec: 35: T19S, R29E

6. COUNTY OR PARISH

Eddy

7. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FILL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT ON:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) TD & Logging & Prod. Csg.

(Note: Report results of multiple completions on Well Completion or Recalculation Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and open part (omit in this work).)

9/29/88 TD 7 7/8" hole to 5800' @ 4:00 AM on 9/29/88 & circ, RU Schlumberger & ran DLL/MSFL, CN/LDT, EPT, RMS & Calip logs, loggers TD @ 5798', RD Schlumberger @ 3:30 AM on 9/30/88, begin laying down drill pipe.

9/30/88 RU Dowell Schlumberger & ran 140 jts (5795.88') 5 $\frac{1}{2}$ " 15.5# J-55 LT&C, set @ 5795', cemented in 2 stages, 1st stage: 103 sks 35/65 POZA, 6% D-20, 8# D-44, 2% S-1, $\frac{1}{4}$ # D-29, tail-in w/595 sks STD, 5# D-44, .5% D-127, PD @ 7:58 PM, 2nd stage: 1897 sks 35/65 POZA, 6% D-20, 8# D-44, 2% S-1, $\frac{1}{4}$ # D-29, PD @ 11:50 PM, set DV Tool @ 2987', ran temp survey, cement top @ 500' FS, begin 1" @ 500' w/320 sks 35/65 POZ, circ 10 sks, finish 1" @ 6:00 AM on 10/1/88, RD L&M #1, released L&M Rig #1 @ 2:00 PM on 10/1/88.

CARLSBAD OFFICE
AREA RECORDERS

OCT 5 11 14 AM '88

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED Cathy BatleyTITLE Drilling/Production SecretaryDATE 9/30/88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:TITLE _____ DATE OCT 17 1988

SJS

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO