

BUREAU OF LAND MANAGEMENT

NM-24160

SUNDRY NOTICES & ID REPORTS ON WELLS

(Do not use this form for proposals to drill or recomplete wells in a different formation.
Use "APPLICATION FOR PERMIT" for such proposals.)

ON WELL ☒ GAS WELL ☐ OTHER ☐

DEC 21 '88

NAME OF OPERATOR

Siete Oil & Gas Corporation

ADDRESS OF OPERATOR

P.O. Box 2523

O. G. D.
ARTESIA, OFFICE

Roswell, New Mexico 88202-2523

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

(See also space 17 below.)

At surface 660' FSL & 1910' FEL, SW $\frac{1}{4}$ SE $\frac{1}{4}$, Unit Letter O

1. SURF CORRELATION DATA

2. DATA ON LEASE DATA

Osage Federal

3. WELL NO.

3

10. ROAD AND POOL OR TRACT

Parkway Delaware

11. SEC. T. R. N. OR BLM. AND COUNTY OR AREA

Sec. 35: T19S, R29E

16. PERMIT NO.

30-015-26007

18. ELEVATIONS (Show whether SP, ST, OR GR.)

3322' GR

19. COUNTY OR PARISH

Eddy

20. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐REPAIR WELL ☐(Other) ☐WELL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDONMENT ☐CHANGE PLANE ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Perf. Acidize & Frac ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☐

(NOTE: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and open ports used in this work.)

11/17/88

RU Dowell Schlumberger & Schlumberger, ran CBL on interval 4933'-2510', perfed interval 4201'-4222' w/15 perfs, TIH w/tension pkr, SN & tbg, spot 1 $\frac{1}{2}$ bbls acid across perfs, set pkr @ 4094', formation broke @ 1900, acidized w/1000 gal 15% HCl, AIR-3 BPM, AIP-1750, balled out 4100, surge balls & finish flush @ 3 BPM @ 1750 PSI, ISIP-1113, flowback & swab.

11/18/88

Fraced w/17,000 gal 30# XL, 2000# 100 mesh, 27,000# 20/40, 12,000# 12/20, AIR-7.2 BPM, AIP-2200, max 3200, FPIP-1400, ISIP-1150, @ 5 min-1012, @ 10 min-989, @ 15 min-971, SION, begin swabbing tomorrow.

ACCEPTED FOR RECORD

DEC 16 1988

EB

CARLSBAD, NEW MEXICO

RECEIVED
NOV 25 11 23 AM '88
CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Cathy BotleyTITLE Drilling/Production SecretaryDATE 11/23/88

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side