

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

30-015-26019

7. Lease Name or Unit Agreement Name

Schoonmaker "ST."

8. Well No.

4

9. Pool name or Wildcat

Turkey track, QN.GB.SA.

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

John Schoonmaker

O. C. D.

ARTESIA, OFFICE

3. Address of Operator

20 Gary Drive. Artesia, New Mexico 88210

4. Well Location

Unit Letter L : 2310 Feet From The South Line and 440 Feet From The West Line

Section 12 Township 19S Range 29E NMPM EDDY County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)

3375'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-30-88: Spud 15" hole with cable tool rig.

12-17-88: Reached total depth of 300ft.

12-19-88: Ran 8 joints of 45#, 10-3/4", J-55 casing set at 300ft.

Cemented with Halliburton with 300sx. premium plus neat at 14.8#/sx.

Left 30ft. cement in casing. Plug down at 4:00 PM. Did not circulate.

Ran wireline and found top of cement at 70ft.

12-20-88: Poured ready mix to surface, took approx. 4 yards. W.O.C. 24hrs.

12-21-88: Drill 27ft. of cement to shoe. And bailed dry. Wait 1 hour and went in hole with bailer, came out dry (casing O.K.).

12-22-88: Drill 1ft. of formation. Clean out with bailer. Wait 1 hour and went in hole with bailer, came out dry (cement job O.K.). went in hole with bit and began drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charles E. Graham TITLE Operations mng. DATE 12-24-88

TYPE OR PRINT NAME Charles E. Graham TELEPHONE NO. 396-6108

(This space for State Use)

Original Signed By

APPROVED BY Mike Williams TITLE  DATE JAN 5 1989

CONDITIONS OF APPROVAL, IF ANY: