

SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS		
				NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Delaware	4000'	4400'	Mudlog shows of oil & gas.	Rustler T/Salt B/Salt T/Yates T/Delaware	310' 450' 1140' 1305' 3540'	+ 3014' + 2874' + 2184' + 2019' - 216'