State Of New Mexico Energy, Minerals and Natural Resources Department Port C:10 Prime Revise 1:09 State Of New Mexico Energy, Minerals and Natural Resources Department Port C:10 Prime Revise 1:09 STRICT: PO. The 1999, Hode, NM 8220 OIL CONSERVATION DIVISION PC. Dav 2028 Santa Fe, New Mexico 87504-2088 STRICTI PO. Dave DD, Aresia, NM 8210 SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS Control of Colspan="2">Control of New Mexico Strong of Colspan="2">Control of Colspan= Colspan="2">Control of Colspan="2">Control	1	-		asr	
DISTINCT: DOIL CONSERVATION DIVISION P.O. Box 2088 Will LAPINO. 30-015-26062 DAMELIONO, Areaia, NM 88210 Santa Fe, New Mexico 87504-2088 Image: Construct of the construction of the consthe construction of the construction of the construction	to Appropriate			Form C-103 PP	
DISTRICTION PROTOCHED NATERIA, NM 8210 Santa Fe, New Mexico 87504-2088 Indicat Type of Length Submittion of the District Property of Length Submittion of the District Property of Length (DO NOT USE THIS FORM FOR FORDERS ON WELLS (DO NOT USE THIS FORM FOR FORDERS TO DELEGATION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DELEGATION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DESCRIPTION OF DEPENDENCE USE ADD (DO NOT USE THIS FORM FOR FORDERS TO DESCRIPTION OF DESCRIPTION O	DISTRICT I OIL CONSERVATION DIVISION				
DISTRICT III 1000 bits barcer Rea, Asse, NM 87410 A state (A Cau Lear No. VP-298 SUNDRY MOTICES AND REPORTS ON WELLS. (DO NOT USE THIS FORM FOR FORCES TO BULL ON TO DEPENDENCE TO (FORM C-101) FOR SUCH PROFOSALS.) There of Well STORENON, USE AND PROFOSALS.) There of Well STORENON (Store Well PROFOSALS.) There of Well Store Store Well Store Store Well Store Store Store Store Store Store Store Well Store Store Well Store Store Well Store Store	DISTRICT II Santa Fe. New Mexico 87504-2088			***************************************	
The 298 VIDE 298 (DO NOT USE THIS FORM YOR PROPOSALS TO BULL ON TO DESERVENCE DUE VIDE BACK TOA DIFFERENT RESERVOR. USE APPLICATION OF VIDE APPLICATION OF VIDE BACK TOA DIFFERENT RESERVOR. USE APPLICATION OF VIDE APPLICATION OF VID				STATE X FEE	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEFENSE REALLY BAUG BACK TOA DIFFERENT RESERVOR. USE "APPLICATION FOR PROPERTY." 7. Lesse Name of Data Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Weil Service (FORM C-101) FOR SUCH PROPOSALS.) FOR DATA (FORM C-101) FOR SUCH PROPOSALS.) 2. New Of Operator NATESS PETROLEDIM CORPORATION O. C. D. I 3. Address of Operator NATESS PETROLEDIM CORPORATION O. C. D. I 3. Address of Operator NATESS PETROLEDIM CORPORATION O. C. D. I 3. Address of Operator NATESS PETROLEDIM CORPORATION O. C. D. I 3. Address of Operator NATESS PETROLEDIM CORPORATION O. C. D. I 3. Address of Operator NATESS PETROLEDIM CORPORATION O. C. D. I 4. Wall Lesize NUL Lake Operator NATESS PETROLEDIM CORPORATION O. C. D. I 4. Wall Lake Common The South Lise sed 2310 Peet From The _ East Lise 4. Wall Lake Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALITERING CASING COMMENCE DRILLING OPNS. </td <td colspan="3">1000 Rio Brazos Rd., Aztec, NM 87410</td> <td></td>	1000 Rio Brazos Rd., Aztec, NM 87410				
Will X ormex MAR 20'89 6. Well No. 2. Name of Opension YATES PERCILIUM CORPORATION O. C. D. 1 3. Address of Opension Artessia, NM 88210 Artessia, Ormes 9. Noderick works of Marrow 105 South 4th St., Artesia, NM 88210 Line and 2310 Peet From The East Line and 2310 4. Well Location 0 : 660 Peet From The South Line and 2310 Peet From The East Line and 2310 4. Well Location 0 : 660 Peet From The South Line and 2310 Peet From The East Line and 2310 4. Well Location 0 : 660 Peet From The South Line and 2310 Peet From The East Line and 2310 4. Well Location Under Charter Charter 10 Location County Line and 2310 Peet From The East Line and 2310 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING Commerce And Casing OTHER: Other Production Casing, Perforate, Treat IX 12 beetshe Proposed or Completed Operatio	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name	
VATES PERIOLEUM CORPORATION O. C. D. I Address of Openior Address of Openior 9. Podpic is where a Morrow 4. Wall Location 9. Podpic is where a Morrow 9. Podpic is where a Morrow 4. Wall Location 0. :		X OTHER MA	R 20 '89	Foothills AGH State	
3. Address of Openics 0. Pool of the Start Morrow 105 South 4th St., Artesia, NM 88210 9. Pool of the Start Morrow 4. Well Location 0. :		DRATION	n c D .	8. Well No.	
Unit Letter 0 : 660 Feet From The South Line and 2310 Feet From The East Line Section 20 Township 195 Range 23E NMTM Eddy County 10. Exection 20 Add6.4' GR GR County 4046.4' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: Production Casing, Perforate, Treat XI 12 Describe Proposed or Completed Operations (Clearly state all pertinent deals, and give pertinent date, iacluding estimated date of starting any proposed work) SEE RULE 103. TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C 152 joints 5-1/2" 15.5# J-55 LT&C and 17 joints 5-1/2" State all state all state all perfinent deals, and give perforations state all perfinent deals, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .47 Halad 22A, .37 CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 pai for 3 minutes, held 0K. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½7	4	ART			
Section 20 Township 195 Range 23E NMPM Eddy County 10. Elevation (Show whether DP, RKB, RT, GR, etc.) 4046.4.4' GR 40.46.4' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSECUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: Froduction Casing, Perforate, Treat X 12 Describe Proposed or Completed Operations (Clearly state all pertinent deals, and give pertinent dates, including estimated date of starting any proposed 31 10 ints 5-1/2" 17 # J-55 LT&C (152 joints 5-1/2" 15.5 # J-55 LT&C and 17 joints 5-1/2" 11.1 # J-55 LT&C (152 joints 5-1/2" 17.4 Halad 22A, JX CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug 200 psi for 3 minutes, held 0K. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N ₂ , and 6 ball sealers. Therefore the box is the wet complete to the best of my trowkedge ad belit. True work weto. 505/748-147		50 Fast From The South	Line and 2310	Fort From The East Line	
10. Elevation (Show whether D ⁰ , RKB, RT, GR, etc.) 4046.4' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ALTERING CASING Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ALTER CASING Chance Addition Additio		100	005		
III. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER:	Section ²⁰	rownamp		NMPM Eddy County	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: Production Casing, Perforate. Treat X 12. Describe Proposed or Completed Operations (Clearly state all periment dataits, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C (total 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8308'. Cemented w/500 gal mud flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .47. Halad 22A, .37. CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held OK. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N ₂ , and 6 ball sealers. 1 hereby certify day the information above in true and pomplete to the best of my trooveridge and belief. StornATURE					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: Production Casing, Perforate, Treat X 12. Describe Proposed or Complete Operations (Clearly state all periment datails, and give periment data; including estimated data of starting any proposed work) SEE RULE 1103. TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C (total 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8380'. Cemented w/500 gal mul flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .4% Halad 22A, .3% CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held OK. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N2, and 6 ball sealers. I hereby certify that the information above is true and complete to the test of my trowkedge and belid. structure:					
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: Production Casing, Perforate, Treat X 12 Describe Proposed or Completed Operations (Clearly state all periment datails, and give periment datas, including estimated date of starting any proposed work) SEE RULE 1103. TD TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C (1otal 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8308'. Cemented w/500 gal mud flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .4% Halad 22A, .3% CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held 0K. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N2, and 6 ball sealers. I hereby certify that the information showe is true and 3complete to the best of my knowledge and belidf. stonkartwer Juanita Goodlett TYPE ON FRANKE Juanita Goodlett Original Signed By MAR 2 0 1989 AFROVED BY Mike WHiliatms					
OTHER: OTHER: Production Casing, Perforate, Treat X 12. Describe Proposed or Completed Operations (Clearly state all periment data), and give periment datas, including estimated date of starting any proposed works SEE RULE 1103. TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C 152 joints 5-1/2" 15.5# J-55 LT&C and 17 joints 5-1/2" 17# J-55 LT&C (total 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8308'. Cemented w/500 gal mud flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .4% Halad 22A, .3% CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held 0K. Perforated 10.45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N2, and 6 ball sealers. I hereby certify that the information above is true and complete to the best of my knowledge and belif. Stonwards Juanita Goodlett TYPE OR WINT NAME Juanita Goodlett Original Signed By MAR 2 0 1989 AFROVED BY MAR 2 0 1989					
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C (152 joints 5-1/2" 15.5# J-55 LT&C and 17 joints 5-1/2" 17# J-55 LT&C (cotal 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8308'. Cemented w/500 gal mud flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .4% Halad 22A, .3% CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held 0K. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N ₂ , and 6 ball sealers. I hereby certify that the information above is true and complete to the best of my knowledge and belief. stonATURE Juanita Goodlett mmp. Production Supervisor part 3-17-89 TYPE OR MENT NAME Juanita Goodlett mmp. Production Supervisor part 3-17-89 MAR 2 0 1989 AFROVED BY Original Signed By Mike WHiliarns mute					
work) SEE RULE 1103. TD 8350'. Reached TD 11:45 PM 3-9-89. Ran 200 joints 5-1/2" casing as follows: 31 joints 5-1/2" 17# J-55 LT&C (10cal 8370') casing, set 8350'. J-55 LT&C and 17 joints 5-1/2" 17# J-55 LT&C (10cal 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8308'. Cemented w/500 gal mud flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .4% Halad 22A, .3% CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held 0K. Perforated 10 .45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N2, and 6 ball sealers. Incredy certify that the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge and belief. Stink the information above is true and Domplete to the best of my knowledge a					
joints 5-1/2" 17# J-55 LT&C 152 joints 5-1/2" 15.5# J-55 LT&C and 17 joints 5-1/2" 17# J-55 LT&C (total 8370') casing, set 8350'. Float shoe set 8350'. Float collar set 8308'. Cemented w/500 gal mud flush, 500 gal Flocheck 21. Tailed in w/1200 sx Class H with .4% Halad 22A, .3% CFR-3 and 5#/sx Salt. PD 8:30 PM 3-10-89. Bumped plug to 2900 psi for 3 minutes, held OK. Perforated 10.45" holes 8104-8113'. Acidized perforations 8104-8113' w/1500 gals 7½% MS acid, N ₂ , and 6 ball sealers. I hereby certify that the information above is true and geomplete to the best of my knowledge and belief. SIONATURE: A Control of the set of my knowledge and belief. SIONATURE: A Control of the set of my knowledge and belief. THE Production Supervisor DATE 3-17-89 TYPE OR MINT NAME Juanita Goodlett TELEPHONE NO. 505/748-147 (This space for State Use) Original Signed By Mike Williams THE DATE DATE		erations (Clearly state all pertinent delaus,	ana give pertinent dates, inclu	aing estimatea date of starting any proposed	
SKINATURE Augusta The Production Supervisor Date 3-17-89 TYPE OR FRINT NAME Juanita Goodlett TELEPHIONE NO. 505/748-147 (This space for State Use) Original Signed By MAR 2 0 1989 APPROVED BY Mike Williams THLE Date	joints 5-1/2" 17# J-5 17# J-55 LT&C (total set 8308'. Cemented Class H with .4% Hala to 2900 psi for 3 min Perforated 10 .45" ho	55 LT&C 152 joints 5-1/2 8370') casing, set 8350 w/500 gal mud flush, 50 ad 22A, .3% CFR-3 and 5 nutes, held OK. bles 8104-8113'. Acidia	2" 15.5# J-55 LT& D'. Float shoe s DO gal Flocheck 2 #/sx Salt. PD 8:	AC and 17 joints 5-1/2" set 8350'. Float collar 21. Tailed in w/1200 sx :30 PM 3-10-89. Bumped plug	
	SKINATURE A CINTA TYPE OR FRINT NAME Juani (This space for State Use)	Original Signed By	me Production Su	TELEPTIONE NO. 505/748-147 MAR 2 0 1989	