

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY 18 '89

WELL API NO. 30-015-26074
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. V-1576
7. Lease Name or Unit Agreement Name Parkway 36 State
8. Well No. 3
9. Pool name or Wildcat Und. Parkway Delaware

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator SANTA FE ENERGY OPERATING PARTNERS, L. P.	
3. Address of Operator 500 WEST ILLINOIS, SUITE 500, MIDLAND, TEXAS 79701	
4. Well Location Unit Letter M : 990 Feet From The South Line and 330 Feet From The West Line Section 36 Township 19S Range 29E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3329' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pg. 1 of 2

05-08-89: Ran 78 jts 7", 23#, K-55 ST&C & set @ 3185'. Cmt w/540 sx C 2% CaCl.
PD @ 10:45 AM. WOC. RU CRC & run temp survey. TOC 1850'+. Cut csg.
Run 1" to 1850', tag cmt. Set plug 35 sx C + 5% CaCl. WOC. Run 1"
& tag @ 1850'. Set 2nd plug 35 sx C + 5% CaCl. WOC (tag @ 1850').
Set 3rd plug 35 sx C + 5% CaCl. WOC. Tag plug @ 1780'. Set 4th plug
35 sx + 5% CaCl. WOC. Tag plug @ 1720'. Set 35 sx 5% CaCl. WOC.
Tag cmt @ 17 0'.

05-09-89: Set 35 sx plug C1 C w/5% CaCl₂ @ 1710'. WOC. TIH & tag @ 1619'. Set
35 sx C1 C w/5% CaCl₂. WOC. TIH & tag @ 1514'. Cmt w/100 sx C1 C
w/2% CaCl₂. TOH. LD tbg. WOC. TIH & tag @ 1238'. Cmt w/500 sx
pacesetter lite w/10% salt & 6% gel. TOH. (cont. on attached page)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE SR. PRODUCTION CLERK DATE 5-17-89

TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915 687-3551

(This space for State Use)

Original Signed By
Mike Williams

APPROVED BY _____ TITLE _____ DATE MAY 23 1989

CONDITIONS OF APPROVAL, IF ANY: