

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210

Budget Bureau No. 1004-0135
Expires: March 31, 1993

CISF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

SEP 26 '94

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
YATES PETROLEUM CORPORATION (505) 748-1471 O. C. D.

3. Address and Telephone No.
105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660' FSL & 1980' FWL of Section 26-T19S-R24E (Unit N, SESW)

5. Lease Designation and Serial No.
NM-25865

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Eng TX Federal #2

9. API Well No.
30-015-26189

10. Field and Pool, or Exploratory Area
N. Dagger Draw Upper Penn/
Hoag Tank Morrow

11. County or Parish, State
Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other Abandon Morrow; add perfs & reacidize Canyon	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to abandon Morrow completion and add perforations and reacidize Canyon Dolomite completion as follows:

1. POOH with rods, pump, etc.
2. Set CIBP at 8900' and cap with 35' of cement on top of CIBP to abandon Morrow perforations 8956-8966'.
3. RIH w/4" casing guns and perforate 7628-7666' w/11 holes.
4. RIH w/packer and tubing to 7600'±. Pressure test tubing and packer.
5. Acidize perforations 7618-7685' with 20000 gallons gelled NEFE HCL acid with scale & paraffin inhibitor. Use benzoic acid flakes/rock salt as block.
6. POOH with packer. RIH w/production tubing, pump and rods. Return to production.

14. I hereby certify that the foregoing is true and correct

Signed Rusty Allen Title Production Clerk Date Sept. 15, 1994

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA Title PETROLEUM ENGINEER Date 9/22/94

Conditions of approval, if any: