Form 3160-5 UNI CONTROL OF THE PROPERTY OF T	STATES s F THE INTERIOR	UBMIT IN TRIPL E. Other instructions re-	Form approved. Budget Bureau No. 1(Expires August 31, 1	985 (\) '
BUREAU OF LA	5. LEASE DESIGNATION AND BREIAL NO. NM 26864			
	Art	esis, 88210	6. IF INDIAN, ALLOTTEE OR TI	RIBE NAME
SUNDRY NOTICES AT				
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			N/A	
1. OIL V GAS			7. UNIT AGREEMENT NAME	-
WELL A WELL OTHER		Committee of the same	N/A 8. FARM OR LEASE NAME	
2. NAME OF OPERATOR YATES PETROLEUM CORPORATION	(505)	748-1471	Roden GD Federal	Com
3. ADDRESS OF OPERATOR	(303)		9. WELL NO.	
105 South 4th St., Artesia, NM	88210	DEC 14'89	5	
 LOCATION OF WELL (Report location clearly and i See also space 17 below.) 	10. FIELD AND POOL, OR WILDCAT			
810' FSL & 1980' FWL		O. C. D. ARTESIA, OPPIČE	North Dagger Draw	• •
010 100 0 100	, 500. 27 155 241	Anna many of the	11. SEC., T., E., M., OR BLK. AN SURVEY OR ARMA	TD .
			Unit N, Sec. 24-T	19S-R24E
14. PERMIT NO. 15 ELEVATIONS (Show whether DF, RT, CR, etc.)			12. COUNTY OR PARISH 13. STATE	
30-015-26207 3596' GR			Eddy NM	
		· · · · · · · · · · · · · · · · · · ·		
16. Check Appropriate	Box To Indicate Nature	of Notice, Report, or O	Other Data	
NOTICE OF INTENTION TO: SUBSEQU			JENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALT	ER CASING	WATER SHUT-OFF	BEPAIRING WELL	
FRACTURE TREAT MULTIPLE CO	' ' ' '	PRACTUBE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE ABANDON®		SHOOTING OR ACIDIZING X	ABANDONMENT* ion casing, perfor	ate
REPAIR WELL CHANGE PLAS	(8	(Note: Report results	of multiple completion on Wel	·
	early state all pertinent details		etion Report and Log form.)	erting env
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (CI proposed work. If well is directionally drilled nent to this work.) 	give subsurface locations and	l measured and true vertica	l depths for all markers and z	ones perti-
TD 7855'. Reached TD 11-28-89.	Ran 186 ininte	711 23# & 26# .cas	ing as follows: 4	6 4+0
7" 26# N-80; 7 jts 7" 23# N-80;	115 its 7" 23# J	·55: 15 its 7" 23	# N-80. and 3 ite	0 jts 7" 26#
J-55, casing set at 7855'. Flo	oat shoe set 7855'.	float collar set	7811'. DV tool s	, 20 <i>11</i> et 5452.
Marker joint set @ 7212' to 7205'. Cemented stage I - 1000 gals Flocheck II, 650 sx Class H				
w/5#/sx salt, .4% Halad 22A, .3% CFR-3 (yield 1.18, wt. 15.6). PD 11:45 AM 11-29-89.				
Circ thru DV tool 2 hrs. Stage II - 1000 sx Halliburton Lite w/1/2#/sx Flocele (yield 1.84,				
wt 12.7). Tailed in $w/100$ sx Class H Neat (yield 1.18, wt 15.6). Closed DV tool $w/2550\#$. PD 2:15 PM 11-29-89. Circ 75 sx on 1st stage, no cement on 2nd stage. Drilled out DV tool.				
12-5-89. Perforated 7645-7694	X on 1st stage, no	cement on 2nd s	tage. Drilled out	DV tool.
7672, 73, 74, 78, 81, 84, 86, 9	w/10.50 noies a h nd 7694' Acidi	18 10110WS: /045	, 40, 4/, 48, 49, 3	30, 31,
Reperforated 7643-53' and 7666-	·98' w/4 JSPF - 168	3.50" holes.	gais 20% NETE IN .	z stages.
12-6-89. Acidized perfs 7643-5	3' and 7666-98' w/	15000 gals 20% N	EFE acid.	
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	· 15 25 4 1	DERECTO		·7 *
	Ada		• •	
		•	• •	() []]
	ha le l		:	:=
				C)
	CARISBAL	, NEW ARKICO		
18. I hereby certify that the foregoing is true and co				
SIGNED A PORTE SOULLES		ion Supervisor	DATE 1 2-7-89	9
			DATE	
(This space for Federal or State office use)				
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE	