

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

APR 4 '90

WELL API NO.

30-015-26265

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 25

Township 19S

Range 24E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3582' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Production Casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8000'. Reached TD 3-26-90. Ran 192 joints 7" casing as follows; 10 jts 26# N-80, 21 jts 26# N-55, 23 jts 23# N-80, 124 jts 23# J-55, 11 jts 23# N-80 and 3 jts 26# J-55, casing set at 8000'. Float shoe set 8000', float collar set 7958'. DV tool set 5397'. Cemented in two stages as follows: Stage I - 500 gals Surebond, 800 sx Class H w/.8% CF-14 + 10% Salt + 5#/sx Hiseal (yield 1.19, wt 15.7). PD 8:00 PM 3-27-90. Opened DV tool w/500 psi and circulated 2 hrs. Circulated 75 sx to pit. Stage II - 900 sx Pacesetter Lite w/5#/sx Salt + .4% CF-14 + 1/2#/sx Celloseal + 5#/sx Hiseal (yield 1.98, wt 12.4). Tailed in w/ 100 sx Class H w/.4% CF-14 + 5#/sx Salt (yield 1.19, wt 15.7). PD 12:00 AM 3-28-90. Circulated 125 sx to pit. Bumped plug to 2500 psi for 5 minutes, float and casing held okay. Released rig 3-28-90. WOCU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett

TITLE Production Supervisor

DATE 4-3-90

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

APR 5 1990

CONDITIONS OF APPROVAL, IF ANY: