	DEPARTME OF THE I	
(Do n	SUNDRY NOTICES AND REPO	OPTS ON WERE EIVEN 8 IF INDIAN, ALLOTTER OR TRI
OIL X	GAS WELL OTHER	MAR 5 8 12 AH 190 7. UNIT AGREEMENT HAME
3. ADDRESS OF		AREA H. RECEIVEDS 8. FARM OR LEASE NAME OSage Federal 9. Wall NO.
	OX 2523 Roswell, N  Pr Well (Report location clearly and in accordance to below.)	M 88202-2523
At surface	1650' FNL & 2310' FWL, SE½NW¾	, Unit Letter F MAR 28'90 Parkway Bone Sprin
4. PERMIT NO.	13 SEEVATIONS (Show w	ARTESIA, OFFICE Sec. 34: T195, R2
6.		2' GR Eddy NM icaie Nature of Notice, Report, or Other Data
	NOTICE OF INTENTION TO:	BUBBEQUENT REPORT OF:
PRACTURE SHOOT OR A REPAIR WE (Other)	ACIDIZE ABANDON*  CHANGE PLANS	WATER SHUT-OFF  PRACTURE TREATMENT  SHOOTING OR ACIDIZING  (Other)  (Note: Report results of multiple completion on Well  Completion or Recompletion Report and Log form.)  pertinent details, and give pertinent dates, including estimated date of starting size locations and measured and true vertical depths for all markers and zones
/13/90		55'-4000'), perforated 6968'-7052' w/16 perfs,
/14/90	3.4 @ 1360. 3 57 @ 1250. 2 60	hole w/2% KCl, spot 2 bbls acid over perfs, 2000 gal 15% HCl, formation broke @ 1500 PSI, 3 @ 1190, balled out to 3000 w/18 BS, surge), ISIP-990, @ 5 min-900, @ 10 min-890,
15/90	Fraced w/76,000 gal 20# xL, 2 BPM @ 1250 PSI, FPIP-2180, IS 15 min-1215, flowed for 2 hrs	208,000# Ottawa 16/30 & 32,000# RCS, AIR-25 SIP-1700, @ 5 min-1240, @ 10 min-1220, @ , TP-450, est. 100 BF, left well open to flow.
		ACCEPTED FOR RECORD
		1880 O C (000
		MAR 2 7 1990
l bereby corti	fy that the formula is a	
l bereby certii	fy that the foregoing is true and correct	CARLSBAD, NEW MEXICO  Drlg. & Prod. Tech. 3/2/90

## \*See Instructions on Reverse Side