

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

RECEIVED

MAY 10 '90

Q. C. D.
ARTESIA, OFFICE

DRILL STEM TEST

JOHN AGU #1
Unit C, Sec. 14-T20S-R24E
Eddy County, NM

DST #1 9144-9206' MORROW CLASTIC:: TIMES -- 30-60-60-180-60.
RECOVERY: 167' drilling mud. SAMPLER: .15 cfg, 1850 cc mud
and 100 psi. PRESSURES: IHP 4767; IPF 207-313, ISIP 3058, 2nd
FP 235-252, FSIP 3652, FFP 277-287, FHP 4766.