

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-26306

5. Indicate Type of Lease
STATE ☐ FEE ☐

6. State Oil & Gas Lease No.
L-2634

7. Lease Name or Unit Agreement Name
Merci State No. 1

8. Well No.
#1

9. Pool name or Wildcat Turkey Track,,
7R, Qn, GB, SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐ DEC 17 '90

2. Name of Operator
ACECO PETROLEUM C. C. D.

3. Address of Operator
2106 Richey, Artesia, New Mexico ARTESIA OFFICE

4. Well Location
Unit Letter K : 1760 Feet From The South Line and 1760 Feet From The West Line
Section 12 Township 19 South Range 29 East NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
1746 - Drilling depth

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>7" Intermediate</u> <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-29-90 Halliburton on location 9:00 A.M. - 1397' of 7" 20# casg. in hole
9:49 Tie onto 7" casing with swedge - H2O Ahead 10:00 A.M. - Super flush 101
10:04 - H2O Displacement to spot below casg. 10:13 - Shut down; 11:00 - Tie onto 7" with head and manifold - Attempt to spot collar and
12:00 - Lost 7" Casing in hole - Released .

12-1-90 4:10 P.M. - 1400 lbs pres. - break circulation	4:50 - Tied on 7" casing
4:15 - Pumped H2O	4:54 - Pumped 15 sks fresh water gel
4:22 - Super flush 101	5:08 - Pumped 230 sks H/C
4:23 - Water to displace super flush 101	5:33 - Pumped 200 sks PP Neat
4:34 - Shut down pull - jt	5:34 - Dropped plug
	5:35 Displaced
	5:46 Plug down

12-3-90 Southwest Ready Mix - cemented to surface - All witnessed by OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harold D. Parrish Sr. TITLE Partner DATE 12-14-90
TYPE OR PRINT NAME ACECO PETROLEUM by Harold D. Parrish, Sr. or 746-6156
TELEPHONE NO. 746-4651

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE DEC 27 1990

CONDITIONS OF APPROVAL, IF ANY: