

OIL CONSERVATION DIVISION DISTRICT IL ARTESIA 811 S. FIRST ST. ARTESIA, NM 88210

Jennifer A. Salisbury CABINET SECRETARY

MARCH 17, 1999

YATES PETROLEUM CORP. 105 SOUTH 4TH ST. ARTESIA, NEW MEXICO 88210

RE:30-015-26256 J-23-20-24 YATES PETRO. CORP. HILLVIEW AHE FED. COM. #4 SWD

ATT: YATES PETROLEUM CORPORATION,

ON MAY 21, 1998 THE HILLVIEW AHE FED. COM. #4 FAILED AND ANNUAL BRADENHEAD TEST. AFTER A BRADENHEAD TEST FAILURE A WELL IS GIVEN 90 DAYS TO BEGIN REPAIR. OUR RECORDS INDICATE TEST FAILURE WAS DUE TO PRESSURE ON THE LONGSTRING OF CASING. PLEASE BEGIN REPAIR OF THE HILLVIEW AHE FED. COM. #4 WITHIN 30 DAYS FROM THE DATE OF THIS LETTER.

SINCERELY.

mes Smith fall

MIKE STUBBLEFIELD N.M.O.C.D. FIELD REP. 2