

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-015-26412
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-689
7. Lease Name or Unit Agreement Name: SST
8. Well No. #4
Pool name or Wildcat Millman Queen GB-SA, East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88201 505-623-6601	
4. Well Location Unit Letter F : 1697 feet from the West line and 2030 feet from the North line Section 6 Township 19S Range 29E NMPM Eddy County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3386.7' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

3/29/2000

Set CIBP @ 2100'. Spot 40 sxs on top. TOC 1716'.

3/31/2000

Pull 1287' of 5 1/2" casing.
Spot 55 sxs @ 1344'-1133' tagged.
Spot 45 sxs @ 416'-242' tagged.

4/01/2000

Spot 10 sxs @ 30'-surface.
Install dry hole marker. Circulate 10# mud.
P&A complete.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianna Rodgers TITLE Production Analyst DATE 4/20/2000

Type or print name Dianna Rodgers Telephone No. 505-623-6601
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep I DATE 5-23-00
Conditions of approval, if any:

